



Bridge Inspection Report for Minnehaha County South Dakota **2022**

Structure No. 50-216-015 Jasper Street / Co. Hwy 104



Dell Rapids Township



10/28/22



Repair and Posting Recommendations Bridges Maintained by Local Governments

Structure No. 50-216-015 **Hwy or Street** Jasper St. / Co. Hwy. 104
FA Route No. 6250 **Agency Responsible for Maintenance** Minnehaha Co.
Location 1.2 miles east and 0.2 miles north of Dell Rapids, SD.
Bridge Description 34.0 ft Three Span Continuous Concrete Bridge with Concrete Abutments.
0 Degree Skew - 30.2 ft Roadway Width.
Date Inspected 6/16/2022 **Year Built** 1922 - Reconstructed 1966

Posting Recommendations

Single Unit - N.A. tons Current Posting: Not Posted
 Combinator - N.A. tons Legal Loads: No Load Posting Required

Legal Loads Based on Article 6.1.4 of AASHTO "The Manual for Bridge Evaluation", Third Edition

Repair, Rehabilitation, and/or Replacement Recommendations

1. Install bridge railing rubrails and approach guardrails as required.
2. Install NE object marker that is damaged and lying on ground.
3. Straighten the 1st delineator along the NW approach.
4. Clean and repair/patch areas of scaling, spalling, and exposed rebar on the underside of the concrete slab.
5. Clean and repair/patch areas of deterioration and honeycombing at the center columns in the east & west bents.
6. Patch hole in slab along south side of original slab in west span.
7. Monitor underside of concrete slab for continued deterioration.
8. **Structure is currently in the 5-year capital improvement plan & scheduled for future replacement.**

The South Dakota Department of Transportation is required by Federal Statute to maintain an inventory of all bridges on all public traveled routes. Therefore, it is important that County and City Officials report any changes on bridges on their system. Examples of changes which should be reported are: Replacement of an existing bridge with pipe or new bridge, safety updated, rehabilitation or repair of an existing bridge etc. Changes should be reported to: South Dakota Department of Transportation, Local Government Assistance, Pierre, South Dakota, 57501.

RECOMMENDATIONS MADE BY: _____


 Chris Brozik, P.E.

DATE: 6/16/2022

Bridge Inspection Report

Structure No.	50-216-015	Maint. Proj. No.	
Feature Carried	Jasper St. / Co. Hwy. 104	County	Minnehaha Co.
Feature Crossed	Unnamed Tributary to Big Sioux River		
Location	1.2 miles east and 0.2 miles north of Dell Rapids, SD.		
Bridge Description	34.0 ft Three Span Continuous Concrete Bridge with Concrete Abutments.		
	0 Degree Skew - 30.2 ft Roadway Width.		
Date Inspected	Inspectors	Temperature	
06/16/22	Chris Brozik, P.E. & Anthony Peters	63 Deg F	

Approach - Items 65.00 - 65.09

1. ALIGNMENT - The vertical and horizontal alignments are good.
2. CONDITION - Bituminous - Smooth.
3. JOINTS - None
4. GUARD RAILS - None
5. EMBANKMENT - Good - No sign of erosion behind the wingwalls. There is a CMP culvert underneath the roadway approach off the SW corner of the structure which discharges into the channel just off the end of the SW wingwall. There is some erosion evident off the end of the culvert, but it does not appear to be endangering the structure.
6. DRAINAGE - The drainage of the roadway is good.
7. SIGNAGE - Type 2 Object Markers - At all four (4) corners of the structure. The NE object marker is damaged and lying on the ground.

Delineators - There are four (4) delineators located off the NW, NE, and SE corners and three (3) delineators located off the SW corner of the structure. The first delineator along the SW approach was not installed due to a residential entrance. The 1st delineator along the NW approach is slightly bent forward. Otherwise, the delineators appear to be in relatively good condition.
8. GPS COORDINATES . Latitude: 43.82602 North Longitude: -96.69411 West

Structure Number 50-216-015Date 06/16/22

Deck - Items 58.00 - 58.17

1. DECK CONDITION - CRACKING, SCALING, SPALLING, AND DELAMINATIONS -

Cast-in-place concrete - The top surface of the concrete slab is not visible due to the bituminous overlay.
2. OVERLAY - TYPE, THICKNESS, AND CONDITION -

Bituminous - Approximate 6-inch average depth, smooth. Light vegetation growth is evident along edges of overlay.
3. JOINTS - OPENINGS - None
4. DRAINS - None
5. CURBS AND MEDIAN - Cast-in-place concrete - Some vertical hairline cracks and areas of light scaling and rust staining are evident throughout. Overall, the concrete curbs appear to be in relatively good condition.
6. SIDEWALKS - None
7. RAILING OR BARRIER - The railings consist of a painted steel channel mounted on painted double steel angle posts. The paint on the railing members appears to be in fair to good condition with some areas of surface rust evident.
8. LIGHTING - None
9. UTILITIES - None
10. DECK DELAMINATION SURVEY - Unable to perform a deck delamination survey due to the bituminous overlay.

Structure Number 50-216-015Date 06/16/22

Superstructure - Items 59.00 - 59.20

- | | |
|--|---|
| 1. UNDERSIDE OF DECK - | Cast-in-place concrete - The original structure appears to have been widened approximately 7 ft along both sides. A significant amount of spalling is evident along the south side of the original slab in all spans and along north side of original slab in east span which have exposed reinforcing steel. The exposed portions of the reinforcing steel are heavily rusted with plating evident and moderate section loss, but does not appear to be affecting structure capacity at the time of inspection. Stalactites are evident along south side of original slab at the west and center spans. There are longitudinal hairline cracks and areas of light scaling evident throughout the original portion of the slab with a couple areas of efflorescence evident. Areas of light scaling are also evident on the underside of the widening portions of the concrete slab. There is an approximate 3"x5"x10" deep hole in the south side of the original slab in the west span which appears to extend to the bottom of the bituminous overlay. |
| 2. BEARING DEVICES - | None |
| 3. GIRDERS OR BEAMS - STIFFENERS, WELDS, SPLICES, AND ETC. - | None |
| 4. DIAPHRAGMS - | None |
| 5. TRUSSES - MAIN MEMBERS, PORTALS, BRACING, GUSSET PLATES, AND ETC. - | None |
| 7. RIVETS OR BOLTS - | None |
| 8. WELDS - | None |
| 9. PAINT - | None |
| 10. DRAINAGE SYSTEM - | None |
| 11. UTILITIES - | None |
| 12. REACTION UNDER LOAD - | No excessive deflection under heavy vehicle load. |
| 13. COLLISION DAMAGE - | None evident. |

Structure Number 50-216-015Date 06/16/22**Substructure - Items 60.00 - 60.05**

1. ABUTMENTS -
 - A. WINGWALLS - The wingwalls consist of cast-in-place concrete and are direct extensions of the backwalls. Some chips are evident along the tops of the wingwalls. It appears these chips occurred during the placement of the riprap. Overall, the wingwalls appear to be in relatively good condition.
 - B. BACKWALLS - The backwalls consist of cast-in-place concrete. Both ends of the original backwalls were extended when the structure was widened. There are some areas of honeycombing evident in the original portions of the backwalls. A spall is evident at the north end of the original portion of the east backwall. The widening portions of the backwalls appear to be in relatively good condition.
 - C. FOOTINGS - None
 - D. PILE CAPS - None
2. PIERS OR BENTS -
 - A. CAPS - Cast-in-place concrete - The original concrete caps were extended when the structure was widened. Some areas of light to moderate scaling are evident throughout and some vertical hairline cracks are evident over the columns. Overall, the concrete bent caps appear to be in satisfactory condition.
 - B. COLUMNS - Cast-in-place concrete - There are five (5) concrete columns per bent (10 total columns). The original bents consisted of three (3) columns. The original end columns were added onto and an additional column was added at the ends of the bents when the structure was widened. A significant amount of deterioration and a lack of consolidation is evident towards the bottom of the center column in both bents.
 - C. FOOTINGS - The portion of the concrete footings at columns #2 - #5 in both bents have been exposed, but do not appear to be undermined.
3. GROUT PADS - None
4. ANCHOR BOLTS - None
5. PILES - None visible.
6. BRACING - None
7. PAINT - None

Structure Number 50-216-015

Date 06/16/22

Substructure - Items 60.00 - 60.05 (Continued)

8. MOVEMENT -

- A. PLUMBNESS - Everything appears vertical.
- B. SETTLEMENT - None evident.
- C. HORIZONTAL - None evident.

Structure Number 50-216-015Date 06/16/22**Channel and Channel Protection - Items 61.00 - 61.09**

1. CHANNEL -
 - A. ALIGNMENT - The channel alignment is fair. It appears a RHF skew would better fit the channel.
 - B. VEGETATION - Good
 - C. SCOUR - None
 - D. DEBRIS - None
 - E. FLOW LINE - Well defined.
2. EMBANKMENT EROSION - Minor amount of embankment erosion is evident in both the upstream and downstream channels.
3. WATERWAY ADEQUACY - Appears adequate.
4. SPUR DIKES & JETTIES - None
5. WING DAMS - None
6. RIP RAP - A significant amount of riprap has been placed along NW channel bank, in front of the wingwalls, and at the ends of the backwalls at the corners of the structure.
7. OBSERVED HIGH WATER ELEVATION - Appears to be approximately 2 to 3 feet below the bottom of the concrete slab.
8. STREAM BED - Appears relatively stable.

ELEMENT LEVEL INSPECTION (Main Span)

Str. No.: 50-216-015		Maint. Proj. No.:	
Feature Carried: Jasper St. / Co. Hwy. 104		MRM:	County: Minnehaha Co.
Feature Crossed: Unnamed Tributary to Big Sioux River			
Location: 1.2 miles east and 0.2 miles north of Dell Rapids, SD.			
Bridge Description: 34.0 ft Three Span Continuous Concrete Bridge with Concrete Abutments. 0 Degree Skew - 30.2 ft Roadway Width.			
Length: 34.0 ft	Roadway width: 30.2 ft	Deck width: 34.2 ft	
Deck Area : Length x Deck Width = 1,163 Sq. ft		Skew: 0 degrees	
Inspector(s): Chris Brozik, P.E. & Anthony Peters			Date: 06/16/22

Element Condition States

Elem Num	Element Description	Env	Quantity	Units	Quantity in Condition State				
					1	2	3	4	
38	Reinforced Concrete Slab	2	1,163	SF	425	630	108		
1090	Exposed Rebar	2		SF			68		
1080	Delamination/Spall/Patched Area	2		SF		430			
1130	Cracking	2		SF		200			
1120	Efflorescence/Rust Staining	2		SF			40		
1190	Abrasion/Wear	2		SF					
1900	Distortion	2		SF					
4000	Settlement	2		SF					
6000	Scour	2		SF					
7000	Damage	2		SF					
814	AC w/o Membrane Overlay	2	1,027	SF	1,027				
3230	Effectiveness	2		SF					
3210	Delam./Spall/Patched Area/Pothole	2		SF					
3220	Crack	2		SF					
7000	Damage	2		SF					
205	Columns, Reinforced Concrete	2	10	EA		8	2		
1090	Exposed Rebar	2		EA					
1080	Delamination/Spall/Patched Area	2		EA		8	2		
1130	Cracking	2		EA					
1120	Efflorescence/Rust Staining	2		EA					
1190	Abrasion/Wear	2		EA					
1900	Distortion	2		EA					
4000	Settlement	2		EA					
6000	Scour	2		EA					
7000	Damage	2		EA					
215	Abutment, Reinforced Concrete	2	68	LF	28	40			
1090	Exposed Rebar	2		LF					
1080	Delamination/Spall/Patched Area	2		LF		40			
1130	Cracking	2		LF					

Bridge Inspection Digital Photo Log

Structure No. **50-216-015**

Photo Number:	Date:	Description:
1	6/16/2022	Approach looking East
2	6/16/2022	Approach looking West
3	6/16/2022	Profile looking North
4	6/16/2022	Profile looking South
5	6/16/2022	CMP Culvert Outlet at SW Corner of Structure
6	6/16/2022	NE Object Marker Damaged and on Ground
7	6/16/2022	1st NW Approach Delineator Slightly Bent
8	6/16/2022	Top of Bituminous Overlay looking West
9	6/16/2022	South Bridge Rail
10	6/16/2022	North Bridge Rail
11	6/16/2022	Typical Rail Post Condition
12	6/16/2022	Underside of Existing Slab, South side of East Span
13	6/16/2022	Underside of Existing Slab, North side of East Span
14	6/16/2022	Underside of Existing Slab, South side of Center Span
15	6/16/2022	Underside of Existing Slab, North side of Center Span
16	6/16/2022	Underside of Existing Slab, South side of West Span
17	6/16/2022	Underside of Existing Slab, North side of West Span
18	6/16/2022	Hole in underside of Slab, South side of West Span
19	6/16/2022	West Backwall
20	6/16/2022	East Backwall
21	6/16/2022	NE Backwall Spall
22	6/16/2022	Typical Configuration of Bent
23	6/16/2022	West Bent Center Column Honeycombing
24	6/16/2022	East Bent Center Column Honeycombing
25	6/16/2022	Typical Exposed Concrete Footing (West Bent Column #3 shown)
26	6/16/2022	Upstream Channel looking NW
27	6/16/2022	Downstream Channel looking South
28	6/16/2022	Riprap along NW Channel Bank
29	6/16/2022	Riprap in front of SE Wingwall
30	6/16/2022	Riprap in front of NE Wingwall



50-216-015_2022_1_CDI_Approach looking East



50-216-015_2022_2_CDI_Approach looking West



50-216-015_2022_3_CDI_Profile looking North



50-216-015_2022_4_CDI_Profile looking South




50-216-015_2022_5_CDI_CMP Culvert Outlet at SW Corner of Structure



50-216-015_2022_6_CDI_NE Object Marker Damaged and on Ground



50-216-015_2022_7_CDI_1st NW Approach Delineator Slightly Bent



50-216-015_2022_8_CDI_Top of Bituminous Overlay looking West



50-216-015_2022_9_CDI_South Bridge Rail



50-216-015_2022_10_CDI_North Bridge Rail



50-216-015_2022_11_CDI_Typical Rail Post Condition



50-216-015_2022_12_CDI_Underside of Existing Slab, South side of East Span



50-216-015_2022_13_CDI_Underside of Existing Slab, North side of East Span



50-216-015_2022_14_CDI_Underside of Existing Slab, South side of Center Span



50-216-015_2022_15_CDI_Underside of Existing Slab, North side of Center Span



50-216-015_2022_16_CDI_Underside of Existing Slab, South side of West Span



50-216-015_2022_17_CDI_Underside of Existing Slab, North side of West Span



50-216-015_2022_18_CDI_Hole in underside of Slab, South side of West Span



50-216-015_2022_19_CDI_West Backwall



50-216-015_2022_20_CDI_East Backwall



50-216-015_2022_21_CDI_NE Backwall Spall



50-216-015_2022_22_CDI_Typical Configuration of Bent



50-216-015_2022_23_CDI_West Bent Center Column Honeycombing



50-216-015_2022_24_CDI_East Bent Center Column Honeycombing



50-216-015_2022_25_CDI_Typical Exposed Concrete Footing (West Bent Column #3 shown)



50-216-015_2022_26_CDI_Upstream Channel looking NW



50-216-015_2022_27_CDI_Downstream Channel looking South



50-216-015_2022_28_CDI_Riprap along NW Channel Bank



50-216-015_2022_29_CDI_Riprap in front of SE Wingwall



50-216-015_2022_30_CDI_Riprap in front of NE Wingwall

CHANNEL PROFILE


MINNEHAHA COUNTY

STR. NO. 50-216-015

MEASUREMENTS TAKEN FROM THE TOP OF: **RAIL NORTH**
 MEASUREMENTS TAKEN ON THE INLET SIDE OF THE STRUCTURE:

WATER ELEV: **12.6**

		2016	2018	7/1/2020	6/16/2022	ABUT./BENT	
West End	0	7.7	7.7	7.7	8.6	1	0
	5	9.0	9.0	9.4	9.5	2	10
	10	12.2	12.8	12.8	12.8	3	21
	15	13.0	12.2	13.4	13.4	4	32
	20	12.6	12.5	12.6	12.9		
	25	8.9	8.8	10.1	10.1		
East End	30	7.7	7.7	7.9	8.1	Top of RAIL to bottom of Superstructure 3.5 ft.	
	32	8.1	8.3	8.2	8.3		



Note: Only Partial Set of Construction Plans are enclosed in SDDOT bridge inspection file.



General Bridge Data		Status
(8) STR NO : 50-216-015	(27) YEAR BUILT : 1922	SUFF RATE : 48.50
(7) FACILITY : JASPER ST, HWY 104	(106) RECONSTR : 1966	FED SUFF RATE : 63.40
(6) FEAT INTER : TRIB TO BIG SIOUX RV	(49) STR LENGTH : 34.00 ft	FED SR DATE : 03/14/2022
(9) LOCATION : 1.2E & 0.2N DELL RAPIDS	NBIS BRIDGE LENGTH : 32.00 ft	DEFICIENCY : S
INTERCHANGE : N	(48) MAX SPAN LENGTH : 11.00 ft	CANDIDATE : H
SECTION(S) : 10 -1 -1 -1	(43A) MATERIAL : 2 Concrete Continuous	
TOWNSHIP(S) : 104N -1	(43B) DESIGN : 01 Slab	Deck Data
RANGE(S) : 49W -1	SD STR TYPE : X020	(108A) WEARING SURFACE : 6 Bituminous
(2) REGION : Mitchell	(107) DECK STR TYPE : 1 Concrete-Cast-in-Place	DECK PROTECTION : None
(3) COUNTY : 50 MINNEHAHA	(52) DECK WIDTH : 34.20 ft	OVERLAY THICKNESS : 6.00 in
(21) CUSTODIAN : 2 County Hwy Agency	(51) BRIDGE RDWY WIDTH : 30.20 ft	DECK DELAM AREA : 0.00 sq ft
(22) OWNER : 2 County Hwy Agency	(32) APPR RDWY WIDTH : 24.00 ft	DECK DELAM DATE :
MAINT PROJ :	(50A) LT SIDEWALK WIDTH : 0.00 ft	DECK SURVEY :
(42A) SERV TYPE ON : 1 Highway	(50B) RT SIDEWALK WIDTH : 0.00 ft	CHLORIDE : N
(42B) SERV TYPE UND : 5 Waterway	(34) SKEW : 0.00°	RESTEEL DEPTH : N
(103) TEMP STRUCTURE : Unknown (NBI)	SKEW DIR :	ELECTRO POTENT : N
(99) BORDER BRIDGE STR NO : -1	(45) NO MAIN SPANS : 3	Load Rating Data
(98A) NEIGHBOR STATE : Unknown (P)	(46) NO APPR SPANS : 0	(41) OPER STATUS : A Open, no restriction
(98B) PERCENT SHARE : -2.00	(31) DESIGN LOAD : 0 Unknown	(66) INV HS20 : 21.60 tons
Highway Carried (NBI 5)	(33) BRIDGE MEDIAN : 0 No median	(65) METHOD : 0 Field eval and docs
(5B) ROUTE PREFIX : 4 County Hwy	(35) STR FLARED : 0 No flare	(64) OP HS20 : 36.00 tons
(5C) LEVEL OF SERVICE : 1 Mainline	Box Culvert Data	(63) METHOD : 0 Field eval and docs
(5D) ROUTE NUMBER : 00000	BOX CULVERT SIZE : 0 X 0 X 0	TRUCK TYPE 3 : 24.00 tons
(5E) DIRECT SUFFIX : 0 N/A (NBI)	FILL HT OVER BOX : 0.00 ft	TRUCK TYPE 3S2 : 40.00 tons
MRM ENGLISH : 0.00	LENGTH OF LONGEST CELL : 0.00 ft	TRUCK TYPE 3-2 : 46.00 tons
POSTED SPEED : 55 MPH	Rail Data	NRL : 40.00 tons
SCHOOL BUS RT : Y	(36) SAFETY FEAT : 0000	SHV-4 : 27.00 tons
MAIL RT : Y	BRIDGE RAIL 1 : 06 -STL DISCONT CHANNEL RAIL	SHV-5 : 31.00 tons
(104) NHS SYSTEM : 0 Not on NHS	RAIL TRANS 1 : 00 - NO TRANSITION PROVIDED	SHV-6 : 34.80 tons
FA ROUTE : 6250	APPR RAIL 1 : 00 - NO APPROACH RAIL	SHV-7 : 38.80 tons
(26) FUNC CLASS : 07 Rural Mjr Collector	APPR RAIL TERM 1 : 00 - NO TERMINALS PROVIDED	EV2 : tons
(28A) LANES : 2	NBI Prop Work	EV3 : tons
(102) DIRECTION TRAFFIC : 2 2-way traffic	(75A) WORK TYPE : 31 Repl-Load Capacity	BARS NO : JDG
(105) FED LANDS HWY : 0 N/A (NBI)	(75B) WORK BY : 1 Contract	Hydraulics
(19) DETOUR : 9.00 mi	(76) IMPROV LENGTH : 184.06 ft	DRAINAGE AREA : 3.35 sq mi
(29) ADT TOTAL : 1120.00	(94) BRIDGE IMPROV COST : \$263,756.00	OBSERV HW ELEV : 0.00 ft
(30) YEAR OF ADT : 2021	(95) RDWAY IMPROV COST : \$26,376.00	YEAR : 01/01/1901
(109) % TRUCK : 3.00 %	(96) TOTAL PROJECT COST : \$449,960.00	DESIGN FREQ : 0.00
(53) MIN V CLR RT : 99.99 ft	(97) YEAR OF IMPROV COST : \$2,018.00	DESIGN FLOW : 0.00 cfs
(53) MIN V CLR LT : 0.00 ft	(114) ADT FUTURE : 1400.00	DESIGN VELOCITY : 0.00 fps
(10) MAX V CLR RT : 99.99 ft	(115) YEAR OF ADT FUTURE : 2036	DESIGN AREA : 0.00 sq ft
(10) MAX V CLR LT : 0.00 ft	Steel Paint	DESIGN YEAR :
(47) HORIZ V CLR RT : 30.20 ft	UNDERCOAT :	DESIGN HW ELEV : ft
(47) HORIZ V CLR LT : 0.00 ft	TOPCOAT :	100 YEAR FLOW : 0.00 cfts
GIS Data	YEAR :	100 YEAR HW ELEV : ft
LATITUDE : 43.82602	COLOR :	V MAX : fps
LONGITUDE : -96.69411		SCOUR SCREENING : 2
DATE : 03/28/2016		SCOUR RATING : U
COMMENT : Calculated GIS INFO		TOPEKA SHINER : N
		Rail Paint
		UNDERCOAT : LEAD-BASED PAINT
		TOP COAT : LEAD-BASED PAINT
		YEAR :

COLOR : ORANGE

Highway Carried (Under Record)

(5A) RECORD TYPE : (54) MIN V CLR RT :
 (5B) ROUTE PREFIX : (54) MIN V CLR LT :
 (5C) LEVEL OF SERVICE : (10) MAX V CLR RT :
 (5D) ROUTE NUMBER : (10) MAX V CLR LT :
 (5E) DIRECT SUFFIX : (47) HORIZ CLR RT :
 MRM : (47) HORIZ CLR LT :
 ADM JUR : (55) OUT UNDCLR RT :
 (104) NHS SYSTEM : (55) OUT UNDCLR LT :
 FA ROUTE : (56) MED UNDCLR RT :
 (26) FUNC CLASS : (56) MED UNDCLR LT :
 (28B) LANES :
 (101) DIRECTION OF TRAFFIC :
 (19) DETOUR LENGTH : mi
 (29) ADT :
 (30) ADT YEAR :

Project Number	PCN	Date Done
NA	none	01/01/1922

Inspection

GENERAL COMMENT : -1
 REGION COMMENT : -1
 FREE COMMENT : -1

INSPECTION TYPE	LAST INSPECTION DATE	REQUIRED	INSPECTION FREQUENCY	NEXT INSP DATE
NBI	06/16/2022		24 month(s)	06/16/2024
FRACTURE CRITICAL	NA	N	NA	NA
UNDERWATER	NA	N	NA	NA
SPECIAL	NA	N	NA	NA
ELEMENT INSPECTION	06/16/2022		24 month(s)	06/16/2024

INSPKEY : BHSS
 APPRAIS BY : CLB
 APPRAIS DATE : 10/03/2022
 QA INSPECTOR :
 QA INSP DATE :
 LAST INSPECTION BY :
 CONSULTANT CODE : CIVIL DESIGN

Condition Ratings

(58) DECK : 4
 (59) SUPER : 4
 (60) SUB : 5
 (62) CULVERT : N
 (113) SCOUR : U
 (61) CHANNEL : 6
 APPROACH : 7 -1

Appraisal Ratings


STR APPR : 4 -1
 DECK GEOM : 5 -1
 UNDERCLR : N -1
 WATERWAY : 8 -1
 APPR ALIGN : 8 -1
 BR POST : 5 LEGAL LOADS
 SCOUR SCREENING : 2
 SCOUR RATING : U

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Re Concrete Slab	MAIN	38	2	1163.00	sq.ft	425.00	630.00	108.00	0.00
<p>Cast-in-place concrete - The top surface of the concrete slab is not visible due to the bituminous overlay.</p> <p>Cast-in-place concrete - The original structure appears to have been widened approximately 7 ft along both sides. A significant amount of spalling is evident along the south side of the original slab in all spans and along north side of original slab in east span which have exposed reinforcing steel. The exposed portions of the reinforcing steel are heavily rusted with plating evident and moderate section loss, but does not appear to be affecting structure capacity at the time of inspection. Stalactites are evident along south side of original slab at the west and center spans. There are longitudinal hairline cracks and areas of light scaling evident throughout the original portion of the slab with a couple areas of efflorescence evident. Areas of light scaling are also evident on the underside of the widening portions of the concrete slab. There is an approximate 3"x5"x10" deep hole in the south side of the original slab in the west span which appears to extend to the bottom of the bituminous overlay.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	430.00	sq.ft	0.00	430.00	0.00	0.00
-									
Exposed Rebar	MAIN	1090	2	68.00	sq.ft	0.00	0.00	68.00	0.00
-									
Efflorescence/Rust Staining	MAIN	1120	2	40.00	sq.ft	0.00	0.00	40.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	200.00	sq.ft	0.00	200.00	0.00	0.00
-									
AC w/o Membrane Overlay	MAIN	814	2	1,027.00	sq.ft	1,027.00	0.00	0.00	0.00
Bituminous - Approximate 6-inch average depth, smooth. Light vegetation growth is evident along edges of overlay.									
Re Conc Column	MAIN	205	2	10.00	each	0.00	8.00	2.00	0.00
<p>Cast-in-place concrete - There are five (5) concrete columns per bent (10 total columns). The original bents consisted of three (3) columns. The original end columns were added onto and an additional column was added at the ends of the bents when the structure was widened. A significant amount of deterioration and a lack of consolidation is evident towards the bottom of the center column in both bents.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	10.00	each	0.00	8.00	2.00	0.00
-									
Re Conc Abutment	MAIN	215	2	68.00	ft	28.00	40.00	0.00	0.00
<p>The backwalls consist of cast-in-place concrete. Both ends of the original backwalls were extended when the structure was widened. There are some areas of honeycombing evident in the original portions of the backwalls. A spall is evident at the north end of the original portion of the east backwall. The widening portions of the backwalls appear to be in relatively good condition.</p> <p>The wingwalls consist of cast-in-place concrete and are direct extensions of the backwalls. Some chips are evident along the tops of the wingwalls. It appears these chips occurred during the placement of the riprap. Overall, the wingwalls appear to be in relatively good condition.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	40.00	ft	0.00	40.00	0.00	0.00
-									
Re Conc Pier Cap	MAIN	234	2	68.00	ft	68.00	0.00	0.00	0.00
<p>Cast-in-place concrete - The original concrete caps were extended when the structure was widened. Some areas of light to moderate scaling are evident throughout and some vertical hairline cracks are evident over the columns. Overall, the concrete bent caps appear to be in satisfactory condition.</p>									
Metal Bridge Railing	MAIN	330	2	68.00	ft	68.00	0.00	0.00	0.00
<p>The railings consist of a painted steel channel mounted on painted double steel angle posts. The paint on the railing members appears to be in fair to good condition with some areas of surface rust evident.</p>									
Lead Based Paint	MAIN	816	2	196.00	sq.ft	196.00	0.00	0.00	0.00
-									


Action	Agency Status	Agency Priority	Assigned to	Rec. Date	Str No	Assigned To	Notes	Target Year
			No					

Bridge Inspection Report for Minnehaha County South Dakota **2022**

Structure No. 50-219-015 Jasper Street / Co. Hwy 104



Dell Rapids Township



10/28/22



Repair and Posting Recommendations Bridges Maintained by Local Governments

Structure No. 50-219-015 **Hwy or Street** Jasper St. / Co. Hwy. 104
FA Route No. 6250 **Agency Responsible for Maintenance** Minnehaha Co.
Location 1.5 miles east and 0.2 miles north of Dell Rapids, SD.
Bridge Description 36.3 ft Two Span Continuous Concrete Bridge with Concrete Abutments.
30 Degree LHF Skew - 24.3 ft Roadway Width.
Date Inspected 6/16/2022 **Year Built** 1938

Posting Recommendations

Single Unit - N.A. tons Current Posting: Not Posted
 Combinator - N.A. tons Legal Loads: No Load Posting Required

Legal Loads Based on Article 6.1.4 of AASHTO "The Manual for Bridge Evaluation", Third Edition

Repair, Rehabilitation, and/or Replacement Recommendations

1. Install bridge railing rubrails and approach guardrails as required.
2. Install 1st NE and 2nd SE approach delineators that are damaged or missing.
3. Clear the deck drains as required.
4. Completely remove and replace the damaged section of the north concrete bridge railing as required.
5. Repair the scaling on the north column at the center bent.
6. Monitor cracking, efflorescence, and stalactites along edges of concrete slab.
7. **Structure is currently in the 5-year capital improvement plan & scheduled for future replacement.**

The South Dakota Department of Transportation is required by Federal Statute to maintain an inventory of all bridges on all public traveled routes. Therefore, it is important that County and City Officials report any changes on bridges on their system. Examples of changes which should be reported are: Replacement of an existing bridge with pipe or new bridge, safety updated, rehabilitation or repair of an existing bridge etc. Changes should be reported to: South Dakota Department of Transportation, Local Government Assistance, Pierre, South Dakota, 57501.

RECOMMENDATIONS MADE BY: _____


 Chris Brozik, P.E.

DATE: 6/16/2022

Bridge Inspection Report

Structure No.	50-219-015	Maint. Proj. No.	
Feature Carried	Jasper St. / Co. Hwy. 104	County	Minnehaha Co.
Feature Crossed	Unnamed Tributary to Big Sioux River		
Location	1.5 miles east and 0.2 miles north of Dell Rapids, SD.		
Bridge Description	36.3 ft Two Span Continuous Concrete Bridge with Concrete Abutments.		
	30 Degree LHF Skew - 24.3 ft Roadway Width.		
Date Inspected	Inspectors	Temperature	
06/16/22	Chris Brozik, P.E. & Anthony Peters	66 Deg F	

Approach - Items 65.00 - 65.09

1. ALIGNMENT - The vertical and horizontal alignments are good. There is a T-intersection approximately 100 ft east of the structure.
2. CONDITION - Bituminous - Smooth. There is a bituminous patch along north half of east bridge end.
3. JOINTS - None
4. GUARD RAILS - A portable concrete barrier curb section has been placed off of the west end of the north railing. It appears a vehicle impact occurred at the end of the bridge railing.
5. EMBANKMENT - Good - No sign of erosion behind the wingwalls.
6. DRAINAGE - The drainage of the roadway is good.
7. SIGNAGE -

Type 3 Object Markers - An object marker has been installed at the west end of the concrete barrier curb extending off of the west end of the north bridge railing. The object marker appears to be in satisfactory condition.

Type 2 Object Markers - There are object markers located at the NE, SW, and SE corners of the structure. The SW marker is leaning backward and facing inward, but is still visible.

Delineators - There are four (4) delineators located off the NW, SW, and SE corners and two (2) delineators located off the NE corner of the structure. The 2nd delineator along the NE approach was not installed due to a roadway intersection. The 1st NE delineator is missing. The 2nd SE delineator is bent downward.
8. GPS COORDINATES - Latitude: 43.82597 North Longitude: -96.68737 West

Structure Number 50-219-015Date 06/16/22

Deck - Items 58.00 - 58.17

1. DECK CONDITION - CRACKING, SCALING, SPALLING, AND DELAMINATIONS -

Cast-in-place concrete - The top surface of the concrete slab is not visible due to the gravel and bituminous overlay.
2. OVERLAY - TYPE, THICKNESS, AND CONDITION -

Gravel and bituminous overlay - Approximate 12-inch average total depth. The bituminous surfacing is relatively smooth.
3. JOINTS - OPENINGS -

None
4. DRAINS -

Deck drains (6-inch dia.) 2 per side, 4 total - All of the deck drains have been covered with gravel and the bituminous overlay surfacing.
5. CURBS AND MEDIAN -

Cast-in-place concrete - The inside faces of the curbs are not visible due to the gravel and bituminous overlay. A moderate amount of scaling is evident along the exterior faces of the curbs and a significant amount of scaling is evident at the ends of the curbs with some areas of exposed rebar.
6. SIDEWALKS -

None
7. RAILING OR BARRIER -

The railings consist of reinforced concrete pigeon hole railings. A moderate to significant amount of scaling is evident throughout with areas of exposed reinforcing steel. It appears a significant vehicle impact occurred at the west end of the north railing. The top concrete railing member, some of the spindles, and the concrete curb have been significantly damaged. A portable concrete barrier curb section has been placed off the west end of the north railing. Steel channels have been installed along the outside face of the railing and are anchored into the concrete barrier curb section. A steel plate has been installed along the inside face of the railing. The steel channels and steel plate are bolted together with bolts running through the pigeon holes. The concrete barrier curb section and steel channels do not provide a railing with the same amount of strength as the original concrete bridge railing before the vehicle impact, but they are providing additional strength to what is provided by the damaged concrete bridge railing. The damaged section of the north concrete bridge railing needs to be completely replaced.
8. LIGHTING -

None
9. UTILITIES -

None
10. DECK DELAMINATION SURVEY -

Unable to perform a deck delamination survey due to the bituminous overlay.

Structure Number 50-219-015Date 06/16/22

Superstructure - Items 59.00 - 59.20

- | | |
|--|--|
| 1. UNDERSIDE OF DECK - | Cast-in-place concrete - Transverse cracks, longitudinal cracks, and areas of map cracking are evident throughout. A significant amount of efflorescence is evident along both the north and south side (outside 1 ft edge) of the concrete slab in the both spans. The efflorescence along edges of slab has advanced to active stalactites dripping along both edges of the east and west spans. The south edge has minor stalactites and the north edge has moderate to substantial stalactites evident. Scaling and some spalls are evident along the bottom exterior edges of the slab at the corners of the structure. |
| 2. BEARING DEVICES - | None |
| 3. GIRDERS OR BEAMS - STIFFENERS, WELDS, SPLICES, AND ETC. - | None |
| 4. DIAPHRAGMS - | None |
| 5. TRUSSES - MAIN MEMBERS, PORTALS, BRACING, GUSSET PLATES, AND ETC. - | None |
| 7. RIVETS OR BOLTS - | None |
| 8. WELDS - | None |
| 9. PAINT - | None |
| 10. DRAINAGE SYSTEM - | Deck drains (6-inch dia.) 2 per side, 4 total - All of the deck drains have been covered with gravel and the bituminous overlay surfacing. |
| 11. UTILITIES - | None |
| 12. REACTION UNDER LOAD - | No excessive deflection under heavy vehicle load. |
| 13. COLLISION DAMAGE - | None evident, except as noted to the north railing. |

Structure Number 50-219-015Date 06/16/22**Substructure - Items 60.00 - 60.05**

1. ABUTMENTS -
 - A. WINGWALLS - Cast-in-place concrete - A moderate to heavy amount of scaling and areas of horizontal hairline cracking are evident on the tops of the wingwalls. Overall, the wingwalls appear to be in satisfactory condition.
 - B. BACKWALLS - Cast-in-place concrete - Some vertical hairline cracks and some scaling along the bottom of the backwalls are evident. Some efflorescence is evident along the top of the backwalls at the ends of the backwalls.
 - C. FOOTINGS - The footing along the bottom of the backwalls can be felt. Previously undermining along the NE backwall footing has been mitigated with riprap.
 - D. PILE CAPS - None
2. PIERS OR BENTS -
 - A. CAPS - Cast-in-place concrete - The bent cap consists of a concrete beam. There are vertical hairline cracks evident between and over the columns. Significant scaling is observed along the north and south ends of the cap.
 - B. COLUMNS - Cast-in-place concrete - There are four (4) concrete columns at the bent. A significant amount of scaling is evident on the north column at the bent. There does not appear to be a significant amount of section loss or exposed reinforcing steel at this time. Vertical hairline cracking is evident in the columns. The south column has efflorescence buildup along the south face which appears to be coming from the underside of slab and from the scaling bent cap.
 - C. FOOTINGS - The north three (3) columns have footings exposed, but do not appear to be undermined. The north column footing appears to be significantly scaling by feeling and probing.
3. GROUT PADS - None
4. ANCHOR BOLTS - None
5. PILES - None visible.
6. BRACING - None
7. PAINT - None
8. MOVEMENT -
 - A. PLUMBNESS - Everything appears vertical.
 - B. SETTLEMENT - None evident.
 - C. HORIZONTAL - None evident.

Structure Number 50-219-015Date 06/16/22

Channel and Channel Protection - Items 61.00 - 61.09

1. CHANNEL -
 - A. ALIGNMENT - The channel alignment is good.
 - B. VEGETATION - Good
 - C. SCOUR - Previously, a minor to moderate amount of scour appeared to be occurring in front of the backwalls as the footings could be felt. The north half of the east backwall footings were beginning to undermine, due to approximately 3 feet of scour. Approximately 2-3 feet of scour at inlet and under north half of structure were evident. This scour and undermining has been mitigated with riprap along the east and west abutments.
 - D. DEBRIS - None
 - E. FLOW LINE - Well defined.
2. EMBANKMENT EROSION - None evident.
3. WATERWAY ADEQUACY - Appears adequate.
4. SPUR DIKES & JETTIES - None
5. WING DAMS - None
6. RIP RAP - Riprap has been placed along the front of the east and west abutments and behind the NW wingwall.
7. OBSERVED HIGH WATER ELEVATION - Appears to be approximately 1 to 2 feet below the bottom of the concrete slab.
8. STREAM BED - Appears to be somewhat scouring on the inlet side of the structure.

ELEMENT LEVEL INSPECTION (Main Span)

Str. No.: 50-219-015	Maint. Proj. No.:
Feature Carried: Jasper St. / Co. Hwy. 104	MRM:
County: Minnehaha Co.	
Feature Crossed: Unnamed Tributary to Big Sioux River	
Location: 1.5 miles east and 0.2 miles north of Dell Rapids, SD.	
Bridge Description: 36.3 ft Two Span Continuous Concrete Bridge with Concrete Abutments. 30 Degree LHF Skew - 24.3 ft Roadway Width.	
Length: 36.3 ft	Roadway width: 24.3 ft
Deck width: 27.3 ft	
Deck Area : Length x Deck Width = 991 Sq. ft	
Skew: 30 degrees LHF	
Inspector(s): Chris Brozik, P.E. & Anthony Peters	Date: 06/16/22

Element Condition States

Elem Num	Element Description	Env	Quantity	Units	Quantity in Condition State				
					1	2	3	4	
38	Reinforced Concrete Slab	2	991	SF		921	70		
1090	Exposed Rebar	2		SF					
1080	Delamination/Spall/Patched Area	2		SF		328	32		
1130	Cracking	2		SF		343			
1120	Efflorescence/Rust Staining	2		SF		250	38		
1190	Abrasion/Wear	2		SF					
1900	Distortion	2		SF					
4000	Settlement	2		SF					
6000	Scour	2		SF					
7000	Damage	2		SF					
814	AC w/o Membrane Overlay	2	882	SF	882				
3230	Effectiveness	2		SF					
3210	Delam./Spall/Patched Area/Pothole	2		SF					
3220	Crack	2		SF					
7000	Damage	2		SF					
205	Columns, Reinforced Concrete	2	4	EA	3	1			
1090	Exposed Rebar	2		EA					
1080	Delamination/Spall/Patched Area	2		EA		1			
1130	Cracking	2		EA					
1120	Efflorescence/Rust Staining	2		EA					
1190	Abrasion/Wear	2		EA					
1900	Distortion	2		EA					
4000	Settlement	2		EA					
6000	Scour	2		EA					
7000	Damage	2		EA					
215	Abutment, Reinforced Concrete	2	54	LF	44	10			
1090	Exposed Rebar	2		LF					
1080	Delamination/Spall/Patched Area	2		LF					
1130	Cracking	2		LF		10			

Bridge Inspection Digital Photo Log

Structure No. **50-219-015**

Photo Number:	Date:	Description:
1	6/16/2022	Approach looking West
2	6/16/2022	Approach looking East
3	6/16/2022	Profile looking South
4	6/16/2022	Profile looking North
5	6/16/2022	1st NE Approach Delineator Missing
6	6/16/2022	2nd SE Approach Delineator Bent
7	6/16/2022	Top of Bituminous Overlay looking West
8	6/16/2022	Bituminous Patch at NE Bridge End
9	6/16/2022	NW Slab and Curb Edge Deterioration and Damage
10	6/16/2022	NE Slab and Curb Edge Deterioration
11	6/16/2022	SE Slab and Curb Edge Deterioration
12	6/16/2022	South Rail
13	6/16/2022	North Rail
14	6/16/2022	NW Portable Concrete Jersey Barrier
15	6/16/2022	SW Rail end Spall with Exposed Rebar
16	6/16/2022	Steel Channel Attached to Backside of NW Railing
17	6/16/2022	Underside of South Edge of Slab in West Span with Stalactites
18	6/16/2022	Underside of South Edge of Slab in East Span with Stalactites
19	6/16/2022	Underside of North Edge of Slab in West Span with Stalactites
20	6/16/2022	Underside of North Edge of Slab in East Span with Stalactites
21	6/16/2022	South Edge of Slab with Efflorescence and Minor Stalactites
22	6/16/2022	North Edge of Slab with Active Stalactite Dripping
23	6/16/2022	Center Bent
24	6/16/2022	North Bent Column Scaling
25	6/16/2022	Center Bent South Column Efflorescence Buildup
26	6/16/2022	Upstream Channel looking North
27	6/16/2022	Downstream Channel looking South
28	6/16/2022	Riprap in front of West Abutment
29	6/16/2022	Riprap in front of East Abutment



50-219-015_2022_1_CDI_Approach looking West



50-219-015_2022_2_CDI_Approach looking East



50-219-015_2022_3_CDI_Profile looking South



50-219-015_2022_4_CDI_Profile looking North



50-219-015_2022_5_CDI_1st NE Approach Delineator Missing



50-219-015_2022_6_CDI_2nd SE Approach Delineator Bent



50-219-015_2022_7_CDI_Top of Bituminous Overlay looking West



50-219-015_2022_8_CDI_Bituminous Patch at NE Bridge end



50-219-015_2022_9_CDI_NW Slab and Curb Edge Deterioration and Damage



50-219-015_2022_10_CDI_NE Slab and Curb Edge Deterioration



50-219-015_2022_11_CDI_SE Slab and Curb Edge Deterioration



50-219-015_2022_12_CDI_South Rail



50-219-015_2022_13_CDI_North Rail



50-219-015_2022_14_CDI_NW Portable Concrete Jersey Barrier



50-219-015_2022_15_CDI_SW Rail end Spall with Exposed Rebar



50-219-015_2022_16_CDI_Steel Channel Attached to Backside of NW Railing



50-219-015_2022_17_CDI_Underside of South Edge of Slab in West Span with Stalactites



50-219-015_2022_18_CDI_Underside of South Edge of Slab in East Span with Stalactites



50-219-015_2022_19_CDI_Underside of North Edge of Slab in West Span with Stalactites



50-219-015_2022_20_CDI_Underside of North Edge of Slab in East Span with Stalactites



50-219-015_2022_21_CDI_South Edge of Slab with Efflorescence and Minor Stalactites



50-219-015_2022_22_CDI_North Edge of Slab with Active Stalactite Dripping



50-219-015_2022_23_CDI_Center Bent



50-219-015_2022_24_CDI_North Bent Column Scaling



50-219-015_2022_25_CDI_Center Bent South Column Efflorescence Buildup



50-219-015_2022_26_CDI_Upstream Channel looking North



50-219-015_2022_27_CDI_Downstream Channel looking South



50-219-015_2022_28_CDI_Riprap in front of West Abutment



50-219-015_2022_29_CDI_Riprap in front of East Abutment

CHANNEL PROFILE


MINNEHAHA COUNTY

STR. NO. 50-219-015

MEASUREMENTS TAKEN FROM THE TOP OF: **RAIL**
 MEASUREMENTS TAKEN ON THE INLET SIDE OF THE STRUCTURE: **NORTH**

WATER ELEV: **9.7**

		2016	2018	7/1/2020	6/16/2022	ABUT./BENT	
West End	0	10.8	10.5	10.6	10.4	1	0
	5	11.1	11.0	12.3	11.2	2	16.5
	10	11.2	11.2	12.9	12.9	3	33
	15	11.3	11.3	12.6	12.4		
	20	11.0	11.1	13.5	12.8		
	25	10.8	10.9	13.9	12.2		
30	10.3	10.4	13.6	10.6	Top of RAIL to bottom of Superstructure 3.6 ft.		
East End	33	9.8	9.8	10.5	9.8		



Note: No Construction Plans are enclosed in SDDOT bridge inspection file.



General Bridge Data		Status
(8) STR NO : 50-219-015	(27) YEAR BUILT : 1938	SUFF RATE : 35.30
(7) FACILITY : JASPER ST, HWY 104	(106) RECONSTR : (1)	FED SUFF RATE : 49.90
(6) FEAT INTER : TRIB TO BIG SIOUX RV	(49) STR LENGTH : 36.30 ft	FED SR DATE : 03/14/2022
(9) LOCATION : 1.5E & 0.2N DELL RAPIDS	NBIS BRIDGE LENGTH : 32.30 ft	DEFICIENCY : S
INTERCHANGE : N	(48) MAX SPAN LENGTH : 18.10 ft	CANDIDATE : P
SECTION(S) : 10 -1 -1 -1	Main Span (43A) MATERIAL : 2 Concrete Continuous (43B) DESIGN : 01 Slab	Deck Data
TOWNSHIP(S) : 104N -1		(108A) WEARING SURFACE : 6 Bituminous
RANGE(S) : 49W -1	SD STR TYPE : X020	DECK PROTECTION : None
(2) REGION : Mitchell	(107) DECK STR TYPE : 1 Concrete-Cast-in-Place	OVERLAY THICKNESS : 12.00 in
(3) COUNTY : 50 MINNEHAHA	(52) DECK WIDTH : 27.30 ft	DECK DELAM AREA : 0.00 sq ft
(21) CUSTODIAN : 2 County Hwy Agency	(51) BRIDGE RDWY WIDTH : 24.30 ft	DECK DELAM DATE :
(22) OWNER : 2 County Hwy Agency	(32) APPR RDWY WIDTH : 24.00 ft	DECK SURVEY :
MAINT PROJ :	(50A) LT SIDEWALK WIDTH : 0.00 ft	CHLORIDE : N
(42A) SERV TYPE ON : 1 Highway	(50B) RT SIDEWALK WIDTH : 0.00 ft	RESTEEL DEPTH : N
(42B) SERV TYPE UND : 5 Waterway	(34) SKEW : 30.00°	ELECTRO POTENT : N
(103) TEMP STRUCTURE : Unknown (NBI)	SKEW DIR : L	Load Rating Data
(99) BORDER BRIDGE STR NO : -1	(45) NO MAIN SPANS : 2	(41) OPER STATUS : A Open, no restriction
(98A) NEIGHBOR STATE : Unknown (P)	(46) NO APPR SPANS : 0	(66) INV HS20 : 21.60 tons
(98B) PERCENT SHARE : -2.00	(31) DESIGN LOAD : 0 Unknown	(65) METHOD : 0 Field eval and docs
Highway Carried (NBI 5)	(33) BRIDGE MEDIAN : 0 No median	(64) OP HS20 : 36.00 tons
(5B) ROUTE PREFIX : 4 County Hwy	(35) STR FLARED : 0 No flare	(63) METHOD : 0 Field eval and docs
(5C) LEVEL OF SERVICE : 1 Mainline	Box Culvert Data	TRUCK TYPE 3 : 24.00 tons
(5D) ROUTE NUMBER : 00000	BOX CULVERT SIZE : 0 X 0 X 0	TRUCK TYPE 3S2 : 40.00 tons
(5E) DIRECT SUFFIX : 0 N/A (NBI)	FILL HT OVER BOX : 0.00 ft	TRUCK TYPE 3-2 : 46.00 tons
MRM ENGLISH : 0.00	LENGTH OF LONGEST CELL : 0.00 ft	NRL : 40.00 tons
POSTED SPEED : 55 MPH	Rail Data	SHV-4 : 27.00 tons
SCHOOL BUS RT : Y	(36) SAFETY FEAT : 0000	SHV-5 : 31.00 tons
MAIL RT : Y	BRIDGE RAIL 1 : 11 - CONC PIGEON HOLE RAIL	SHV-6 : 34.80 tons
(104) NHS SYSTEM : 0 Not on NHS	RAIL TRANS 1 : 00 - NO TRANSITION PROVIDED	SHV-7 : 38.80 tons
FA ROUTE : 6250	APPR RAIL 1 : 00 - NO APPROACH RAIL	EV2 : tons
(26) FUNC CLASS : 07 Rural Mjr Collector	APPR RAIL TERM 1 : 00 - NO TERMINALS PROVIDED	EV3 : tons
(28A) LANES : 2	NBI Prop Work	BARS NO : JDG
(102) DIRECTION TRAFFIC : 2 2-way traffic	(75A) WORK TYPE : 31 Repl-Load Capacity	Hydraulics
(105) FED LANDS HWY : 0 N/A (NBI)	(75B) WORK BY : 1 Contract	DRAINAGE AREA : 1.99 sq mi
(19) DETOUR : 9.00 mi	(76) IMPROV LENGTH : 191.60 ft	OBSERV HW ELEV : 0.00 ft
(29) ADT TOTAL : 1111.00	(94) BRIDGE IMPROV COST : \$274,684.00	YEAR : 01/01/1901
(30) YEAR OF ADT : 2021	(95) RDWAY IMPROV COST : \$27,468.00	DESIGN FREQ : 0.00
(109) % TRUCK : 3.00 %	(96) TOTAL PROJECT COST : \$462,092.00	DESIGN FLOW : 0.00 cfs
(53) MIN V CLR RT : 99.99 ft	(97) YEAR OF IMPROV COST : \$2,018.00	DESIGN VELOCITY : 0.00 fps
(53) MIN V CLR LT : 0.00 ft	(114) ADT FUTURE : 1400.00	DESIGN AREA : 0.00 sq ft
(10) MAX V CLR RT : 99.99 ft	(115) YEAR OF ADT FUTURE : 2036	DESIGN YEAR :
(10) MAX V CLR LT : 0.00 ft	Steel Paint	DESIGN HW ELEV : ft
(47) HORIZ V CLR RT : 24.00 ft	UNDERCOAT :	100 YEAR FLOW : 0.00 cfts
(47) HORIZ V CLR LT : 0.00 ft	TOPCOAT :	100 YEAR HW ELEV : ft
GIS Data	YEAR :	V MAX : fps
LATITUDE : 43.82597	COLOR :	SCOUR SCREENING : 2
LONGITUDE : -96.68737		SCOUR RATING : U
DATE : 03/28/2016		TOPEKA SHINER : N
COMMENT : Calculated GIS INFO		Rail Paint
		UNDERCOAT :
		TOP COAT :
		YEAR :

COLOR :

Highway Carried (Under Record)

(5A) RECORD TYPE : (54) MIN V CLR RT :
 (5B) ROUTE PREFIX : (54) MIN V CLR LT :
 (5C) LEVEL OF SERVICE : (10) MAX V CLR RT :
 (5D) ROUTE NUMBER : (10) MAX V CLR LT :
 (5E) DIRECT SUFFIX : (47) HORIZ CLR RT :
 MRM : (47) HORIZ CLR LT :
 ADM JUR : (55) OUT UNDCLR RT :
 (104) NHS SYSTEM : (55) OUT UNDCLR LT :
 FA ROUTE : (56) MED UNDCLR RT :
 (26) FUNC CLASS : (56) MED UNDCLR LT :
 (28B) LANES :
 (101) DIRECTION OF TRAFFIC :
 (19) DETOUR LENGTH : mi
 (29) ADT :
 (30) ADT YEAR :

Project Number	PCN	Date Done
NA	none	01/01/1938

Inspection

GENERAL COMMENT : -1
 REGION COMMENT : -1
 FREE COMMENT : -1

INSPECTION TYPE	LAST INSPECTION DATE	REQUIRED	INSPECTION FREQUENCY	NEXT INSP DATE
NBI	06/16/2022		24 month(s)	06/16/2024
FRACTURE CRITICAL	NA	N	NA	NA
UNDERWATER	NA	N	NA	NA
SPECIAL	NA	N	NA	NA
ELEMENT INSPECTION	06/16/2022		24 month(s)	06/16/2024

INSPKEY : NJQN
 APPRAIS BY : CLB
 APPRAIS DATE : 10/03/2022
 QA INSPECTOR :
 QA INSP DATE :
 LAST INSPECTION BY :
 CONSULTANT CODE : CIVIL DESIGN

Condition Ratings

(58) DECK : 4
 (59) SUPER : 4
 (60) SUB : 5
 (62) CULVERT : N
 (113) SCOUR : U
 (61) CHANNEL : 7
 APPROACH : 7 -1

Appraisal Ratings

STR APPR : 4 -1
 DECK GEOM : 4 -1
 UNDERCLR : N -1
 WATERWAY : 7 -1
 APPR ALIGN : 8 -1
 BR POST : 5 LEGAL LOADS
 SCOUR SCREENING : 2
 SCOUR RATING : U


Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Re Concrete Slab	MAIN	38	2	991.00	sq.ft	0.00	921.00	70.00	0.00
<p>Cast-in-place concrete - The top surface of the concrete slab is not visible due to the gravel and bituminous overlay.</p> <p>Cast-in-place concrete - Transverse cracks, longitudinal cracks, and areas of map cracking are evident throughout. A significant amount of efflorescence is evident along both the north and south side (outside 1 ft edge) of the concrete slab in the both spans. The efflorescence along edges of slab has advanced to active stalactites dripping along both edges of the east and west spans. The south edge has minor stalactites and the north edge has moderate to substantial stalactites evident. Scaling and some spalls are evident along the bottom exterior edges of the slab at the corners of the structure.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	360.00	sq.ft	0.00	328.00	32.00	0.00
-									
Efflorescence/Rust Staining	MAIN	1120	2	288.00	sq.ft	0.00	250.00	38.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	343.00	sq.ft	0.00	343.00	0.00	0.00
-									
AC w/o Membrane Overlay	MAIN	814	2	882.00	sq.ft	882.00	0.00	0.00	0.00
Gravel base with bituminous surfacing - Approximate 12-inch average total depth. The bituminous surfacing is relatively smooth.									
Re Conc Column	MAIN	205	2	4.00	each	3.00	1.00	0.00	0.00
<p>Cast-in-place concrete - There are four (4) concrete columns at the bent. A significant amount of scaling is evident on the north column at the bent. There does not appear to be a significant amount of section loss or exposed reinforcing steel at this time. Vertical hairline cracking is evident in the columns. The south column has efflorescence buildup along the south face which appears to be coming from the underside of slab and from the scaling bent cap.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	1.00	each	0.00	1.00	0.00	0.00
-									
Re Conc Abutment	MAIN	215	2	54.00	ft	44.00	10.00	0.00	0.00
<p>Cast-in-place concrete - Some vertical hairline cracks and some scaling along the bottom of the backwalls are evident. Some efflorescence is evident along the top of the backwalls at the ends of the backwalls.</p> <p>Cast-in-place concrete - A moderate to heavy amount of scaling and areas of horizontal hairline cracking are evident on the tops of the wingwalls. Overall, the wingwalls appear to be in satisfactory condition.</p>									
Cracking (RC and Other)	MAIN	1130	2	10.00	ft	0.00	10.00	0.00	0.00
-									
Re Conc Pier Cap	MAIN	234	2	27.00	ft	19.00	8.00	0.00	0.00
<p>Cast-in-place concrete - The bent cap consists of a concrete beam. There are vertical hairline cracks evident between and over the columns. Significant scaling is observed along the north and south ends of the cap.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	2.00	ft	0.00	2.00	0.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	6.00	ft	0.00	6.00	0.00	0.00
-									
Re Conc Bridge Railing	MAIN	331	2	72.00	ft	0.00	57.00	6.00	9.00
<p>The railings consist of reinforced concrete pigeon hole railings. A moderate to significant amount of scaling is evident throughout with areas of exposed reinforcing steel. It appears a significant vehicle impact occurred at the west end of the north railing. The top concrete railing member, some of the spindles, and the concrete curb have been significantly damaged. A portable concrete barrier curb section has been placed off the west end of the north railing. Steel channels have been installed along the outside face of the railing and are anchored into the concrete barrier curb section. A steel plate has been installed along the inside face of the railing. The steel channels and steel plate are bolted together with bolts running through the pigeon holes. The concrete barrier curb section and steel channels do not provide a railing with the same amount of strength as the original concrete bridge railing before the vehicle impact, but they are providing additional strength to what is provided by the damaged concrete bridge railing. The damaged section of the north concrete bridge railing needs to be completely replaced.</p>									

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Delamination/Spall/Patched Area	MAIN	1080	2	57.00	ft	0.00	57.00	0.00	0.00
-									
Damage	MAIN	7000	2	15.00	ft	0.00	0.00	6.00	9.00
-									


Action	Agency Status	Agency Priority	Assigned to	Rec. Date	Str No	Assigned To	Notes	Target Year
			No					

Bridge Inspection Report for Minnehaha County South Dakota 2022

Structure No. 50-277-015 Jasper Street / Co. Hwy 104



Logan Township



10/28/22



Repair and Posting Recommendations Bridges Maintained by Local Governments

Structure No. 50-277-015 **Hwy or Street** Jasper St. / Co. Hwy. 104
FA Route No. 6250 **Agency Responsible for Maintenance** Minnehaha Co.
Location 7.3 miles east and 0.2 miles north of Dell Rapids, SD.
Bridge Description 70.8 ft Four Span Continuous Concrete Bridge with Concrete Abutments.
0 Degree Skew - 24.3 ft Roadway Width.
Date Inspected 6/16/2022 **Year Built** 1940

Posting Recommendations

Single Unit - N.A. tons Current Posting: Not Posted
 Combination - N.A. tons Legal Loads: No Load Posting Required


Legal Loads Based on Article 6.1.4 of AASHTO "The Manual for Bridge Evaluation", Third Edition

Repair, Rehabilitation, and/or Replacement Recommendations

1. Straighten 1st NE and 4th SW approach delineators that are bent.
2. Install bridge railing rubrails and approach guardrails as required.
3. Clear deck drains as required.
4. Monitor scour at the bents.
5. **Structure is currently in the 5-year capital improvement plan & scheduled for future replacement.**

The South Dakota Department of Transportation is required by Federal Statute to maintain an inventory of all bridges on all public traveled routes. Therefore, it is important that County and City Officials report any changes on bridges on their system. Examples of changes which should be reported are: Replacement of an existing bridge with pipe or new bridge, safety updated, rehabilitation or repair of an existing bridge etc. Changes should be reported to: South Dakota Department of Transportation, Local Government Assistance, Pierre, South Dakota, 57501.

RECOMMENDATIONS MADE BY: _____


 Chris Brozik, P.E.

DATE: 6/16/2022

Bridge Inspection Report

Structure No. 50-277-015 **Maint. Proj. No.** _____
Feature Carried Jasper St. / Co. Hwy. 104 **County** Minnehaha Co.
Feature Crossed West Pipestone Creek
Location 7.3 miles east and 0.2 miles north of Dell Rapids, SD.
Bridge Description 70.8 ft Four Span Continuous Concrete Bridge with Concrete Abutments.
0 Degree Skew - 24.3 ft Roadway Width.

Date Inspected	Inspectors	Temperature
06/16/22	Chris Brozik, P.E. & Anthony Peters	80 Deg F

Approach - Items 65.00 - 65.09

1. ALIGNMENT - The horizontal and vertical alignments are good.
2. CONDITION - Bituminous - Smooth.
3. JOINTS - None
4. GUARD RAILS - None
5. EMBANKMENT - Good - No erosion is evident behind the wingwalls. Riprap has been placed behind the NW and NE wingwalls.
6. DRAINAGE - The drainage of the roadway is good.
7. SIGNAGE - Type 2 Object Markers - At all four (4) corners of the structure. The object markers appear to be in good condition.

 Delineators - There are four (4) delineators located off of all four (4) corners of the structure. The 1st NE approach delineator and 4th SW approach delineator are bent downward.
8. GPS COORDINATES - Latitude: 43.82635 North Longitude: -96.57830 West

Structure Number 50-277-015Date 06/16/22**Deck - Items 58.00 - 58.17**

1. DECK CONDITION - CRACKING, SCALING, SPALLING, AND DELAMINATIONS -

Cast-in-place concrete - The top surface of the concrete slab is not visible due to the bituminous overlay.
2. OVERLAY - TYPE, THICKNESS, AND CONDITION -

Bituminous - Approximate 5-inch average depth. There are three (3) gouges in overlay toward centerline of eastbound lane due to an apparent piece of dragging equipment.
3. JOINTS - OPENINGS - None
4. DRAINS - Deck drains - The deck drains have been overlaid with the bituminous overlay and are plugged.
5. CURBS AND MEDIAN - Cast-in-place concrete - A significant amount of spalling and scaling is evident along the inside face of the north curb. There is some section loss evident in the face of the north curb over the east bent. The south curb exterior face has a vertical crack over center bent. A moderate amount of scaling is evident along the inside face of the south curb. A significant amount of the spalling and exposed reinforcing steel is evident at the east end of the north and south curbs.
6. SIDEWALKS - None
7. RAILING OR BARRIER - The railings consist of reinforced concrete pigeon hole railings. Several spalls, cracks, and areas of exposed reinforcing steel are evident throughout. The south railing has a moderately to heavily weathered appearance with some moss evident on the surface of the railing. There are some small chips and some scrapes evident at the west end of the south railing. It appears these chips and scrapes are due to a vehicle impact.
8. LIGHTING - None
9. UTILITIES - None
10. DECK DELAMINATION SURVEY - Unable to perform a deck delamination survey due to the bituminous overlay.

Structure Number 50-277-015Date 06/16/22

Superstructure - Items 59.00 - 59.20

- | | |
|--|--|
| 1. UNDERSIDE OF DECK - | Cast-in-place concrete - There are longitudinal hairline cracks evident towards the center portion of the slab. Some areas of minor honeycombing are evident throughout. There is an approximate 4 ft x 8 ft area of map cracking and efflorescence along the north side of the west span. There are several cementitious patches in span #3 from the west. It appears these patches are filling some honeycombed areas. Large spalls, which have exposed reinforcing steel, are evident at several of the deck drain locations. Some of the exposed reinforcing steel is plating with minor section loss. The exposed portions of the reinforcing steel have a heavily rusted appearance. |
| 2. BEARING DEVICES - | None |
| 3. GIRDERS OR BEAMS - STIFFENERS, WELDS, SPLICES, AND ETC. - | None |
| 4. DIAPHRAGMS - | None |
| 5. TRUSSES - MAIN MEMBERS, PORTALS, BRACING, GUSSET PLATES, AND ETC. - | None |
| 7. RIVETS OR BOLTS - | None |
| 8. WELDS - | None |
| 9. PAINT - | None |
| 10. DRAINAGE SYSTEM - | Deck drains - the deck drains have been overlaid with the bituminous overlay and are plugged. |
| 11. UTILITIES - | None |
| 12. REACTION UNDER LOAD - | No excessive deflection under heavy vehicle load. |
| 13. COLLISION DAMAGE - | None evident. |

Structure Number 50-277-015Date 06/16/22**Substructure - Items 60.00 - 60.05**

1. ABUTMENTS -
 - A. WINGWALLS - Cast-in-place concrete - The wingwalls have areas of light to moderate scaling evident, but overall, the wingwalls appear to be in satisfactory condition.
 - B. BACKWALLS - Cast-in-place concrete - Some vertical hairline cracks and areas of light to moderate scaling are evident, but overall, the backwalls appear to be in satisfactory condition.
 - C. FOOTINGS - None
 - D. PILE CAPS - None

2. PIERS OR BENTS -
 - A. CAPS - Cast-in-place concrete - The bent caps consist of concrete beams. There are vertical cracks, slightly bigger than hairline, evident between, and over, the columns. Overall, the bent caps appear to be in relatively good condition.
 - B. COLUMNS - Cast-in-place concrete - There are four (4) concrete columns per bent (12 total columns). Areas of scaling are evident, but overall, the concrete columns appear to be in relatively good condition.
 - C. FOOTINGS - Bent footings are exposed but do not appear to be undermined. It appears they observed scour previously and are actively silting back in.

3. GROUT PADS - None
4. ANCHOR BOLTS - None
5. PILES - None visible.
6. BRACING - None
7. PAINT - None
8. MOVEMENT -
 - A. PLUMBNESS - Everything appears vertical.
 - B. SETTLEMENT - None evident.
 - C. HORIZONTAL - None evident.

Structure Number 50-277-015Date 06/16/22**Channel and Channel Protection - Items 61.00 - 61.09**

1. CHANNEL -
 - A. ALIGNMENT - The channel alignment is good.
 - B. VEGETATION - Good
 - C. SCOUR - Moderate scour of approximately 3 feet at column #1 & #2 footings (2020 - 3'-5' scour) in the west and center bent. Previously observed scour at upstream side of structure has silted back in, but downstream side still has approximately 3 feet of scour. Scour does not appear to be endangering structure at the time of inspection.
 - D. DEBRIS - None
 - E. FLOW LINE - Well defined.
2. EMBANKMENT EROSION - None evident.
3. WATERWAY ADEQUACY - Appears adequate.
4. SPUR DIKES & JETTIES - None
5. WING DAMS - None
6. RIP RAP - None, except as noted behind the NW and NE wingwalls.
7. OBSERVED HIGH WATER ELEVATION - Appears to be approximately 2 to 3 feet below the bottom of the concrete slab.
8. STREAM BED - Appears to have previously scoured at the bent locations and is actively silting back in at the structure location.

ELEMENT LEVEL INSPECTION (Main Span)

Str. No.: 50-277-015	Maint. Proj. No.:
Feature Carried: Jasper St. / Co. Hwy. 104	MRM:
County: Minnehaha Co.	
Feature Crossed: West Pipestone Creek	
Location: 7.3 miles east and 0.2 miles north of Dell Rapids, SD.	
Bridge Description: 70.8 ft Four Span Continuous Concrete Bridge with Concrete Abutments. 0 Degree Skew - 24.3 ft Roadway Width.	
Length: 70.8 ft	Roadway width: 24.3 ft
Deck width: 27.3 ft	
Deck Area : Length x Deck Width = 1,933 Sq. ft	Skew: 0 degrees
Inspector(s): Chris Brozik, P.E. & Anthony Peters	Date: 06/16/22

Element Condition States

Elem Num	Element Description	Env	Quantity	Units	Quantity in Condition State				
					1	2	3	4	
38	Reinforced Concrete Slab	2	1,933	SF	936	989	8		
1090	Exposed Rebar	2		SF			8		
1080	Delamination/Spall/Patched Area	2		SF		22			
1130	Cracking	2		SF		967			
1120	Efflorescence/Rust Staining	2		SF					
1190	Abrasion/Wear	2		SF					
1900	Distortion	2		SF					
4000	Settlement	2		SF					
6000	Scour	2		SF					
7000	Damage	2		SF					
814	AC w/o Membrane Overlay	2	1,720	SF	1,712	8			
3230	Effectiveness	2		SF					
3210	Delam./Spall/Patched Area/Pothole	2		SF					
3220	Crack	2		SF					
7000	Damage	2		SF		8			
205	Columns, Reinforced Concrete	2	12	EA		12			
1090	Exposed Rebar	2		EA					
1080	Delamination/Spall/Patched Area	2		EA		12			
1130	Cracking	2		EA					
1120	Efflorescence/Rust Staining	2		EA					
1190	Abrasion/Wear	2		EA					
1900	Distortion	2		EA					
4000	Settlement	2		EA					
6000	Scour	2		EA					
7000	Damage	2		EA					
215	Abutment, Reinforced Concrete	2	55	LF	12	43			
1090	Exposed Rebar	2		LF					
1080	Delamination/Spall/Patched Area	2		LF		8			
1130	Cracking	2		LF		35			

Bridge Inspection Digital Photo Log

Structure No. **50-277-015**

Photo Number:	Date:	Description:
1	6/16/2022	Approach looking East
2	6/16/2022	Approach looking West
3	6/16/2022	Profile looking North
4	6/16/2022	Profile looking South
5	6/16/2022	1st NE Approach Delineator Bent
6	6/16/2022	4th SW Approach Delineator Bent
7	6/16/2022	Top of Bituminous Overlay looking East
8	6/16/2022	Bituminous Overlay Gouges in Eastbound Lane
9	6/16/2022	SW Concrete Curb and Railing Spall
10	6/16/2022	SE Concrete Curb Spall with Exposed Rebar
11	6/16/2022	NW Concrete Curb Spall
12	6/16/2022	NE Concrete Curb Spall with Exposed Rebar
13	6/16/2022	South Curb and Slab Vertical Crack over Center Bent
14	6/16/2022	North Bridge Rail
15	6/16/2022	South Bridge Rail
16	6/16/2022	Typical Concrete Railing Spalling with Exposed Rebar
17	6/16/2022	Underside of Slab Span #2
18	6/16/2022	Underside of Slab Span #3
19	6/16/2022	Underside of Slab Span #4 Spall with Exposed Rebar at South Deck Drain
20	6/16/2022	Underside of Slab Span #4 Spall with Exposed Rebar at North Deck Drain
21	6/16/2022	West Abutment
22	6/16/2022	East Abutment
23	6/16/2022	Typical Configuration of Bent
24	6/16/2022	West Bent Column #1 (South) Exposed Footing
25	6/16/2022	Upstream Channel looking North
26	6/16/2022	Downstream Channel looking South
27	6/16/2022	Scour at West Bent between Column #1 and #2
28	6/16/2022	Scour at Center Bent Column #1 (South)
29	6/16/2022	Riprap behind NW Wingwall
30	6/16/2022	Riprap behind NE Wingwall



50-277-015_2022_1_CDI_Approach looking East



50-277-015_2022_2_CDI_Approach looking West



50-277-015_2022_3_CDI_Profile looking North



50-277-015_2022_4_CDI_Profile looking South



50-277-015_2022_5_CDI_1st NE Approach Delineator Bent



50-277-015_2022_6_CDI_4th SW Approach Delineator Bent



50-277-015_2022_7_CDI_Top of Bituminous Overlay looking East



50-277-015_2022_8_CDI_Bituminous Overlay Gouges in Eastbound Lane



50-277-015_2022_9_CDI_SW Concrete Curb and Railing Spall



50-277-015_2022_10_CDI_SE Concrete Curb Spall with Exposed Rebar



50-277-015_2022_11_CDI_NW Concrete Curb Spall



50-277-015_2022_12_CDI_NE Concrete Curb Spall with Exposed Rebar



50-277-015_2022_13_CDI_South Curb and Slab Vertical Crack over Center Bent



50-277-015_2022_14_CDI_North Bridge Rail



50-277-015_2022_15_CDI_South Bridge Rail



50-277-015_2022_16_CDI_Typical Concrete Railing Spalling with Exposed Rebar



50-277-015_2022_17_CDI_Underside of Slab Span #2



50-277-015_2022_18_CDI_Underside of Slab Span #3



50-277-015_2022_19_CDI_Underside of Slab Span #4 Spall with Exposed Rebar at South Deck Drain



50-277-015_2022_20_CDI_Underside of Slab Span #4 Spall with Exposed Rebar at North Deck Drain



50-277-015_2022_21_CDI_West Abutment



50-277-015_2022_22_CDI_East Abutment



50-277-015_2022_23_CDI_Typical Configuration of Bent



50-277-015_2022_24_CDI_West Bent Column #1 (South) Exposed Footing



50-277-015_2022_25_CDI_Upstream Channel looking North



50-277-015_2022_26_CDI_Downstream Channel looking South



50-277-015_2022_27_CDI_Scour at West Bent between Column #1 and #2



50-277-015_2022_28_CDI_Scour at Center Bent Column #1 (South)



50-277-015_2022_29_CDI_Riprap behind NW Wingwall



50-277-015_2022_30_CDI_Riprap behind NE Wingwall

CHANNEL PROFILE

MINNEHAHA COUNTY

STR. NO. 50-277-015

MEASUREMENTS TAKEN FROM THE TOP OF: **RAIL**
 MEASUREMENTS TAKEN ON THE INLET SIDE OF THE STRUCTURE: **NORTH**


WATER ELEV: **12.2**

		2018	11/7/2019	7/1/2020	6/16/2022
West End	0	11.5	12.2	13.0	12.4
	10	12.6	12.2	12.5	12.5
	20	12.4	12.9	13.8	13.9
	30	13.1	17.4	14.0	14.6
	40	13.1	18.2	13.5	13.7
	50	11.9	12.0	12.6	12.8
East End	66.8	11.0	11.4	11.9	12.0

ABUT./BENT	
1	0
2	16.1
3	33.4
4	50.7
5	66.8

Top of RAIL to bottom of
Superstructure: 4.4 ft

OUTLET SIDE	7/1/2020	6/16/2022
At Bent 2:	16.0	13.3
At Bent 3:	17.0	13.7
At Bent 4:	12.7	12.7



Note: No Construction Plans are enclosed in SDDOT bridge inspection file.



General Bridge Data		Status
(8) STR NO : 50-277-015	(27) YEAR BUILT : 1940	SUFF RATE : 58.50
(7) FACILITY : JASPER ST, HWY 104	(106) RECONSTR : (1)	FED SUFF RATE : 66.30
(6) FEAT INTER : WEST PIPESTONE CREEK	(49) STR LENGTH : 70.80 ft	FED SR DATE : 03/14/2022
(9) LOCATION : 7.3E & 0.2N DELL RAPIDS	NBIS BRIDGE LENGTH : 66.80 ft	DEFICIENCY :
INTERCHANGE : N	(48) MAX SPAN LENGTH : 17.30 ft	CANDIDATE :
SECTION(S) : 10 -1 -1 -1	(43A) MATERIAL : 2 Concrete Continuous	
TOWNSHIP(S) : 104N -1	(43B) DESIGN : 01 Slab	Deck Data
RANGE(S) : 48W -1	SD STR TYPE : X020	(108A) WEARING SURFACE : 6 Bituminous
(2) REGION : Mitchell	(107) DECK STR TYPE : 1 Concrete-Cast-in-Place	DECK PROTECTION : None
(3) COUNTY : 50 MINNEHAHA	(52) DECK WIDTH : 27.30 ft	OVERLAY THICKNESS : 5.00 in
(21) CUSTODIAN : 2 County Hwy Agency	(51) BRIDGE RDWY WIDTH : 24.30 ft	DECK DELAM AREA : 0.00 sq ft
(22) OWNER : 2 County Hwy Agency	(32) APPR RDWY WIDTH : 24.00 ft	DECK DELAM DATE :
MAINT PROJ :	(50A) LT SIDEWALK WIDTH : 0.00 ft	DECK SURVEY :
(42A) SERV TYPE ON : 1 Highway	(50B) RT SIDEWALK WIDTH : 0.00 ft	CHLORIDE : N
(42B) SERV TYPE UND : 5 Waterway	(34) SKEW : 0.00°	RESTEEL DEPTH : N
(103) TEMP STRUCTURE : Unknown (NBI)	SKEW DIR :	ELECTRO POTENT : N
(99) BORDER BRIDGE STR NO : -1	(45) NO MAIN SPANS : 4	Load Rating Data
(98A) NEIGHBOR STATE : Unknown (P)	(46) NO APPR SPANS : 0	(41) OPER STATUS : A Open, no restriction
(98B) PERCENT SHARE : -2.00	(31) DESIGN LOAD : 0 Unknown	(66) INV HS20 : 21.60 tons
Highway Carried (NBI 5)	(33) BRIDGE MEDIAN : 0 No median	(65) METHOD : 0 Field eval and docs
(5B) ROUTE PREFIX : 4 County Hwy	(35) STR FLARED : 0 No flare	(64) OP HS20 : 36.00 tons
(5C) LEVEL OF SERVICE : 1 Mainline	Box Culvert Data	(63) METHOD : 0 Field eval and docs
(5D) ROUTE NUMBER : 00000	BOX CULVERT SIZE : 0 X 0 X 0	TRUCK TYPE 3 : 24.00 tons
(5E) DIRECT SUFFIX : 0 N/A (NBI)	FILL HT OVER BOX : 0.00 ft	TRUCK TYPE 3S2 : 40.00 tons
MRM ENGLISH : 0.00	LENGTH OF LONGEST CELL : 0.00 ft	TRUCK TYPE 3-2 : 46.00 tons
POSTED SPEED : 55 MPH	Rail Data	NRL : 40.00 tons
SCHOOL BUS RT : Y	(36) SAFETY FEAT : 0000	SHV-4 : 27.00 tons
MAIL RT : Y	BRIDGE RAIL 1 : 11 - CONC PIGEON HOLE RAIL	SHV-5 : 31.00 tons
(104) NHS SYSTEM : 0 Not on NHS	RAIL TRANS 1 : NN - NOT APPLICABLE	SHV-6 : 34.80 tons
FA ROUTE : 6250	APPR RAIL 1 : 00 - NO APPROACH RAIL	SHV-7 : 38.80 tons
(26) FUNC CLASS : 07 Rural Mjr Collector	APPR RAIL TERM 1 : 00 - NO TERMINALS PROVIDED	EV2 : tons
(28A) LANES : 2	NBI Prop Work	EV3 : tons
(102) DIRECTION TRAFFIC : 2 2-way traffic	(75A) WORK TYPE : 31 Repl-Load Capacity	BARS NO : JDG
(105) FED LANDS HWY : 0 N/A (NBI)	(75B) WORK BY : 1 Contract	Hydraulics
(19) DETOUR : 9.00 mi	(76) IMPROV LENGTH : 317.26 ft	DRAINAGE AREA : 10.86 sq mi
(29) ADT TOTAL : 506.00	(94) BRIDGE IMPROV COST : \$454,908.00	OBSERV HW ELEV : 0.00 ft
(30) YEAR OF ADT : 2021	(95) RDWAY IMPROV COST : \$45,491.00	YEAR : 01/01/1901
(109) % TRUCK : 3.00 %	(96) TOTAL PROJECT COST : \$712,559.00	DESIGN FREQ : 0.00
(53) MIN V CLR RT : 99.99 ft	(97) YEAR OF IMPROV COST : \$2,018.00	DESIGN FLOW : 0.00 cfs
(53) MIN V CLR LT : 0.00 ft	(114) ADT FUTURE : 700.00	DESIGN VELOCITY : 0.00 fps
(10) MAX V CLR RT : 99.99 ft	(115) YEAR OF ADT FUTURE : 2036	DESIGN AREA : 0.00 sq ft
(10) MAX V CLR LT : 0.00 ft	Steel Paint	DESIGN YEAR :
(47) HORIZ V CLR RT : 24.00 ft	UNDERCOAT :	DESIGN HW ELEV : ft
(47) HORIZ V CLR LT : 0.00 ft	TOPCOAT :	100 YEAR FLOW : 0.00 cfts
GIS Data	YEAR :	100 YEAR HW ELEV : ft
LATITUDE : 43.82635	COLOR :	V MAX : fps
LONGITUDE : -96.57830		SCOUR SCREENING : 2
DATE : 03/28/2016		SCOUR RATING : U
COMMENT : Calculated GIS INFO		TOPEKA SHINER : Y
		Rail Paint
		UNDERCOAT :
		TOP COAT :
		YEAR :

COLOR :

Highway Carried (Under Record)

(5A) RECORD TYPE : (54) MIN V CLR RT :
 (5B) ROUTE PREFIX : (54) MIN V CLR LT :
 (5C) LEVEL OF SERVICE : (10) MAX V CLR RT :
 (5D) ROUTE NUMBER : (10) MAX V CLR LT :
 (5E) DIRECT SUFFIX : (47) HORIZ CLR RT :
 MRM : (47) HORIZ CLR LT :
 ADM JUR : (55) OUT UNDCLR RT :
 (104) NHS SYSTEM : (55) OUT UNDCLR LT :
 FA ROUTE : (56) MED UNDCLR RT :
 (26) FUNC CLASS : (56) MED UNDCLR LT :
 (28B) LANES :
 (101) DIRECTION OF TRAFFIC :
 (19) DETOUR LENGTH : mi
 (29) ADT :
 (30) ADT YEAR :

Project Number	PCN	Date Done
NA	none	01/01/1940

Inspection

GENERAL COMMENT : -1
 REGION COMMENT : -1
 FREE COMMENT : -1

INSPECTION TYPE	LAST INSPECTION DATE	REQUIRED	INSPECTION FREQUENCY	NEXT INSP DATE
NBI	06/16/2022		24 month(s)	06/16/2024
FRACTURE CRITICAL	NA	N	NA	NA
UNDERWATER	NA	N	NA	NA
SPECIAL	NA	N	NA	NA
ELEMENT INSPECTION	06/16/2022		24 month(s)	06/16/2024

INSPKEY : QZRW
 APPRAIS BY : CLB
 APPRAIS DATE : 10/04/2022
 QA INSPECTOR :
 QA INSP DATE :
 LAST INSPECTION BY :
 CONSULTANT CODE : CIVIL DESIGN

Condition Ratings

(58) DECK : 5
 (59) SUPER : 5
 (60) SUB : 6
 (62) CULVERT : N
 (113) SCOUR : U
 (61) CHANNEL : 6
 APPROACH : 7 -1

Appraisal Ratings

STR APPR : 5 -1
 DECK GEOM : 4 -1
 UNDERCLR : N -1
 WATERWAY : 7 -1
 APPR ALIGN : 8 -1
 BR POST : 5 LEGAL LOADS
 SCOUR SCREENING : 2
 SCOUR RATING : U

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Re Concrete Slab	MAIN	38	2	1933.00	sq.ft	936.00	989.00	8.00	0.00
<p>Cast-in-place concrete - The top surface of the concrete slab is not visible due to the bituminous overlay.</p> <p>Cast-in-place concrete - There are longitudinal hairline cracks evident towards the center portion of the slab. Some areas of minor honeycombing are evident throughout. There is an approximate 4 ft x 8 ft area of map cracking and efflorescence along the north side of the west span. There are several cementitious patches in span #3 from the west. It appears these patches are filling some honeycombed areas. Large spalls, which have exposed reinforcing steel, are evident at several of the deck drain locations. Some of the exposed reinforcing steel is plating with minor section loss. The exposed portions of the reinforcing steel have a heavily rusted appearance.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	22.00	sq.ft	0.00	22.00	0.00	0.00
-									
Exposed Rebar	MAIN	1090	2	8.00	sq.ft	0.00	0.00	8.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	967.00	sq.ft	0.00	967.00	0.00	0.00
-									
AC w/o Membrane Overlay	MAIN	814	2	1,720.00	sq.ft	1,712.00	8.00	0.00	0.00
Bituminous - Approximate 5-inch average depth. There are three (3) gouges in overlay due to an apparent piece of dragging equipment.									
Damage	MAIN	7000	2	8.00	sq.ft	0.00	8.00	0.00	0.00
-									
Re Conc Column	MAIN	205	2	12.00	each	0.00	12.00	0.00	0.00
<p>Cast-in-place concrete - There are four (4) concrete columns per bent (12 total columns). Areas of scaling are evident, but overall, the concrete columns appear to be in relatively good condition.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	12.00	each	0.00	12.00	0.00	0.00
-									
Re Conc Abutment	MAIN	215	2	55.00	ft	12.00	43.00	0.00	0.00
<p>BACKWALLS - Cast-in-place concrete - Some vertical hairline cracks and areas of light to moderate scaling are evident, but overall, the backwalls appear to be in satisfactory condition.</p> <p>WINGWALLS - Cast-in-place concrete - The wingwalls have areas of light to moderate scaling evident, but overall, the wingwalls appear to be in satisfactory condition.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	8.00	ft	0.00	8.00	0.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	35.00	ft	0.00	35.00	0.00	0.00
-									
Re Conc Pier Cap	MAIN	234	2	82.00	ft	67.00	15.00	0.00	0.00
<p>Cast-in-place concrete - The bent caps consist of concrete beams. There are vertical cracks, slightly bigger than hairline, evident between, and over, the columns. Overall, the bent caps appear to be in relatively good condition.</p>									
Cracking (RC and Other)	MAIN	1130	2	15.00	ft	0.00	15.00	0.00	0.00
-									
Re Conc Bridge Railing	MAIN	331	2	142.00	ft	0.00	142.00	0.00	0.00
<p>The railings consist of reinforced concrete pigeon hole railings. Several spalls, cracks, and areas of exposed reinforcing steel are evident throughout. The south railing has a moderately to heavily weathered appearance with some moss evident on the surface of the railing. There are some small chips and some scrapes evident at the west end of the south railing. It appears these chips and scrapes are due to a vehicle impact.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	71.00	ft	0.00	71.00	0.00	0.00
-									

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Exposed Rebar	MAIN	1090	2	30.00	ft	0.00	30.00	0.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	41.00	ft	0.00	41.00	0.00	0.00
-									
7361 Scour Smart Flag	MAIN	7361	2	1.00	each	0.00	1.00	0.00	0.00

CURRENT 2022 INSPECTION - Moderate scour of approximately 3 feet at column #1 & #2 footings (2020 - 3'-5' scour) in the west and center bent. Previously observed scour at upstream side of structure has silted back in, but downstream side still has approximately 3 feet of scour. Scour does not appear to be endangering structure at the time of inspection.

PREVIOUS 2020 INSPECTION - Moderate scour of approximately 3 - 5 feet at column #1 & #2 footings in the west and center bent. Previously observed scour at upstream side of structure has silted back in, but downstream side still has approximately 3 - 5 feet of scour. Scour does not appear to be endangering structure at the time of inspection.

PREVIOUS - (2019 Special) Channel – No apparent bank cutting/erosion.
No stream flow debris observed.
Moderate scour of ~ 4'-5' observed at Bent 3 (See Channel Profile).
Minor scour of ~ 1' observed under east span.

Action	Agency Status	Agency Priority	Assigned to	Rec. Date	Str No	Assigned To	Notes	Target Year
			No					