


Bridge Inspection Report for Minnehaha County South Dakota **2022**

Structure No. 50-219-015 Jasper Street / Co. Hwy 104



Dell Rapids Township



10/28/22



Repair and Posting Recommendations Bridges Maintained by Local Governments

Structure No. 50-219-015 **Hwy or Street** Jasper St. / Co. Hwy. 104
FA Route No. 6250 **Agency Responsible for Maintenance** Minnehaha Co.
Location 1.5 miles east and 0.2 miles north of Dell Rapids, SD.
Bridge Description 36.3 ft Two Span Continuous Concrete Bridge with Concrete Abutments.
30 Degree LHF Skew - 24.3 ft Roadway Width.
Date Inspected 6/16/2022 **Year Built** 1938

Posting Recommendations

Single Unit - N.A. tons Current Posting: Not Posted
 Combinator - N.A. tons Legal Loads: No Load Posting Required

Legal Loads Based on Article 6.1.4 of AASHTO "The Manual for Bridge Evaluation", Third Edition

Repair, Rehabilitation, and/or Replacement Recommendations

1. Install bridge railing rubrails and approach guardrails as required.
2. Install 1st NE and 2nd SE approach delineators that are damaged or missing.
3. Clear the deck drains as required.
4. Completely remove and replace the damaged section of the north concrete bridge railing as required.
5. Repair the scaling on the north column at the center bent.
6. Monitor cracking, efflorescence, and stalactites along edges of concrete slab.
7. **Structure is currently in the 5-year capital improvement plan & scheduled for future replacement.**

The South Dakota Department of Transportation is required by Federal Statute to maintain an inventory of all bridges on all public traveled routes. Therefore, it is important that County and City Officials report any changes on bridges on their system. Examples of changes which should be reported are: Replacement of an existing bridge with pipe or new bridge, safety updated, rehabilitation or repair of an existing bridge etc. Changes should be reported to: South Dakota Department of Transportation, Local Government Assistance, Pierre, South Dakota, 57501.

RECOMMENDATIONS MADE BY: _____


 Chris Brozik, P.E.

DATE: 6/16/2022

Structure Number 50-219-015Date 06/16/22

Deck - Items 58.00 - 58.17

1. DECK CONDITION - CRACKING, SCALING, SPALLING, AND DELAMINATIONS -

Cast-in-place concrete - The top surface of the concrete slab is not visible due to the gravel and bituminous overlay.
2. OVERLAY - TYPE, THICKNESS, AND CONDITION -

Gravel and bituminous overlay - Approximate 12-inch average total depth. The bituminous surfacing is relatively smooth.
3. JOINTS - OPENINGS - None
4. DRAINS - Deck drains (6-inch dia.) 2 per side, 4 total - All of the deck drains have been covered with gravel and the bituminous overlay surfacing.
5. CURBS AND MEDIAN - Cast-in-place concrete - The inside faces of the curbs are not visible due to the gravel and bituminous overlay. A moderate amount of scaling is evident along the exterior faces of the curbs and a significant amount of scaling is evident at the ends of the curbs with some areas of exposed rebar.
6. SIDEWALKS - None
7. RAILING OR BARRIER - The railings consist of reinforced concrete pigeon hole railings. A moderate to significant amount of scaling is evident throughout with areas of exposed reinforcing steel. It appears a significant vehicle impact occurred at the west end of the north railing. The top concrete railing member, some of the spindles, and the concrete curb have been significantly damaged. A portable concrete barrier curb section has been placed off the west end of the north railing. Steel channels have been installed along the outside face of the railing and are anchored into the concrete barrier curb section. A steel plate has been installed along the inside face of the railing. The steel channels and steel plate are bolted together with bolts running through the pigeon holes. The concrete barrier curb section and steel channels do not provide a railing with the same amount of strength as the original concrete bridge railing before the vehicle impact, but they are providing additional strength to what is provided by the damaged concrete bridge railing. The damaged section of the north concrete bridge railing needs to be completely replaced.
8. LIGHTING - None
9. UTILITIES - None
10. DECK DELAMINATION SURVEY - Unable to perform a deck delamination survey due to the bituminous overlay.

Structure Number 50-219-015Date 06/16/22

Superstructure - Items 59.00 - 59.20

- | | |
|--|--|
| 1. UNDERSIDE OF DECK - | Cast-in-place concrete - Transverse cracks, longitudinal cracks, and areas of map cracking are evident throughout. A significant amount of efflorescence is evident along both the north and south side (outside 1 ft edge) of the concrete slab in the both spans. The efflorescence along edges of slab has advanced to active stalactites dripping along both edges of the east and west spans. The south edge has minor stalactites and the north edge has moderate to substantial stalactites evident. Scaling and some spalls are evident along the bottom exterior edges of the slab at the corners of the structure. |
| 2. BEARING DEVICES - | None |
| 3. GIRDERS OR BEAMS - STIFFENERS, WELDS, SPLICES, AND ETC. - | None |
| 4. DIAPHRAGMS - | None |
| 5. TRUSSES - MAIN MEMBERS, PORTALS, BRACING, GUSSET PLATES, AND ETC. - | None |
| 7. RIVETS OR BOLTS - | None |
| 8. WELDS - | None |
| 9. PAINT - | None |
| 10. DRAINAGE SYSTEM - | Deck drains (6-inch dia.) 2 per side, 4 total - All of the deck drains have been covered with gravel and the bituminous overlay surfacing. |
| 11. UTILITIES - | None |
| 12. REACTION UNDER LOAD - | No excessive deflection under heavy vehicle load. |
| 13. COLLISION DAMAGE - | None evident, except as noted to the north railing. |

Structure Number 50-219-015Date 06/16/22**Substructure - Items 60.00 - 60.05**

1. ABUTMENTS -
 - A. WINGWALLS - Cast-in-place concrete - A moderate to heavy amount of scaling and areas of horizontal hairline cracking are evident on the tops of the wingwalls. Overall, the wingwalls appear to be in satisfactory condition.
 - B. BACKWALLS - Cast-in-place concrete - Some vertical hairline cracks and some scaling along the bottom of the backwalls are evident. Some efflorescence is evident along the top of the backwalls at the ends of the backwalls.
 - C. FOOTINGS - The footing along the bottom of the backwalls can be felt. Previously undermining along the NE backwall footing has been mitigated with riprap.
 - D. PILE CAPS - None
2. PIERS OR BENTS -
 - A. CAPS - Cast-in-place concrete - The bent cap consists of a concrete beam. There are vertical hairline cracks evident between and over the columns. Significant scaling is observed along the north and south ends of the cap.
 - B. COLUMNS - Cast-in-place concrete - There are four (4) concrete columns at the bent. A significant amount of scaling is evident on the north column at the bent. There does not appear to be a significant amount of section loss or exposed reinforcing steel at this time. Vertical hairline cracking is evident in the columns. The south column has efflorescence buildup along the south face which appears to be coming from the underside of slab and from the scaling bent cap.
 - C. FOOTINGS - The north three (3) columns have footings exposed, but do not appear to be undermined. The north column footing appears to be significantly scaling by feeling and probing.
3. GROUT PADS - None
4. ANCHOR BOLTS - None
5. PILES - None visible.
6. BRACING - None
7. PAINT - None
8. MOVEMENT -
 - A. PLUMBNESS - Everything appears vertical.
 - B. SETTLEMENT - None evident.
 - C. HORIZONTAL - None evident.

Structure Number 50-219-015Date 06/16/22

Channel and Channel Protection - Items 61.00 - 61.09

1. CHANNEL -
 - A. ALIGNMENT - The channel alignment is good.
 - B. VEGETATION - Good
 - C. SCOUR - Previously, a minor to moderate amount of scour appeared to be occurring in front of the backwalls as the footings could be felt. The north half of the east backwall footings were beginning to undermine, due to approximately 3 feet of scour. Approximately 2-3 feet of scour at inlet and under north half of structure were evident. This scour and undermining has been mitigated with riprap along the east and west abutments.
 - D. DEBRIS - None
 - E. FLOW LINE - Well defined.
2. EMBANKMENT EROSION - None evident.
3. WATERWAY ADEQUACY - Appears adequate.
4. SPUR DIKES & JETTIES - None
5. WING DAMS - None
6. RIP RAP - Riprap has been placed along the front of the east and west abutments and behind the NW wingwall.
7. OBSERVED HIGH WATER ELEVATION - Appears to be approximately 1 to 2 feet below the bottom of the concrete slab.
8. STREAM BED - Appears to be somewhat scouring on the inlet side of the structure.

ELEMENT LEVEL INSPECTION (Main Span)

Str. No.: 50-219-015	Maint. Proj. No.:
Feature Carried: Jasper St. / Co. Hwy. 104	MRM:
County: Minnehaha Co.	
Feature Crossed: Unnamed Tributary to Big Sioux River	
Location: 1.5 miles east and 0.2 miles north of Dell Rapids, SD.	
Bridge Description: 36.3 ft Two Span Continuous Concrete Bridge with Concrete Abutments. 30 Degree LHF Skew - 24.3 ft Roadway Width.	
Length: 36.3 ft	Roadway width: 24.3 ft
Deck width: 27.3 ft	
Deck Area : Length x Deck Width = 991 Sq. ft	
Skew: 30 degrees LHF	
Inspector(s): Chris Brozik, P.E. & Anthony Peters	Date: 06/16/22

Element Condition States

Elem Num	Element Description	Env	Quantity	Units	Quantity in Condition State				
					1	2	3	4	
38	Reinforced Concrete Slab	2	991	SF		921	70		
1090	Exposed Rebar	2		SF					
1080	Delamination/Spall/Patched Area	2		SF		328	32		
1130	Cracking	2		SF		343			
1120	Efflorescence/Rust Staining	2		SF		250	38		
1190	Abrasion/Wear	2		SF					
1900	Distortion	2		SF					
4000	Settlement	2		SF					
6000	Scour	2		SF					
7000	Damage	2		SF					
814	AC w/o Membrane Overlay	2	882	SF	882				
3230	Effectiveness	2		SF					
3210	Delam./Spall/Patched Area/Pothole	2		SF					
3220	Crack	2		SF					
7000	Damage	2		SF					
205	Columns, Reinforced Concrete	2	4	EA	3	1			
1090	Exposed Rebar	2		EA					
1080	Delamination/Spall/Patched Area	2		EA		1			
1130	Cracking	2		EA					
1120	Efflorescence/Rust Staining	2		EA					
1190	Abrasion/Wear	2		EA					
1900	Distortion	2		EA					
4000	Settlement	2		EA					
6000	Scour	2		EA					
7000	Damage	2		EA					
215	Abutment, Reinforced Concrete	2	54	LF	44	10			
1090	Exposed Rebar	2		LF					
1080	Delamination/Spall/Patched Area	2		LF					
1130	Cracking	2		LF		10			

Bridge Inspection Digital Photo Log

Structure No. **50-219-015**

Photo Number:	Date:	Description:
1	6/16/2022	Approach looking West
2	6/16/2022	Approach looking East
3	6/16/2022	Profile looking South
4	6/16/2022	Profile looking North
5	6/16/2022	1st NE Approach Delineator Missing
6	6/16/2022	2nd SE Approach Delineator Bent
7	6/16/2022	Top of Bituminous Overlay looking West
8	6/16/2022	Bituminous Patch at NE Bridge End
9	6/16/2022	NW Slab and Curb Edge Deterioration and Damage
10	6/16/2022	NE Slab and Curb Edge Deterioration
11	6/16/2022	SE Slab and Curb Edge Deterioration
12	6/16/2022	South Rail
13	6/16/2022	North Rail
14	6/16/2022	NW Portable Concrete Jersey Barrier
15	6/16/2022	SW Rail end Spall with Exposed Rebar
16	6/16/2022	Steel Channel Attached to Backside of NW Railing
17	6/16/2022	Underside of South Edge of Slab in West Span with Stalactites
18	6/16/2022	Underside of South Edge of Slab in East Span with Stalactites
19	6/16/2022	Underside of North Edge of Slab in West Span with Stalactites
20	6/16/2022	Underside of North Edge of Slab in East Span with Stalactites
21	6/16/2022	South Edge of Slab with Efflorescence and Minor Stalactites
22	6/16/2022	North Edge of Slab with Active Stalactite Dripping
23	6/16/2022	Center Bent
24	6/16/2022	North Bent Column Scaling
25	6/16/2022	Center Bent South Column Efflorescence Buildup
26	6/16/2022	Upstream Channel looking North
27	6/16/2022	Downstream Channel looking South
28	6/16/2022	Riprap in front of West Abutment
29	6/16/2022	Riprap in front of East Abutment



50-219-015_2022_1_CDI_Approach looking West



50-219-015_2022_2_CDI_Approach looking East



50-219-015_2022_3_CDI_Profile looking South



50-219-015_2022_4_CDI_Profile looking North



50-219-015_2022_5_CDI_1st NE Approach Delineator Missing



50-219-015_2022_6_CDI_2nd SE Approach Delineator Bent



50-219-015_2022_7_CDI_Top of Bituminous Overlay looking West



50-219-015_2022_8_CDI_Bituminous Patch at NE Bridge end



50-219-015_2022_9_CDI_NW Slab and Curb Edge Deterioration and Damage



50-219-015_2022_10_CDI_NE Slab and Curb Edge Deterioration



50-219-015_2022_11_CDI_SE Slab and Curb Edge Deterioration



50-219-015_2022_12_CDI_South Rail



50-219-015_2022_13_CDI_North Rail



50-219-015_2022_14_CDI_NW Portable Concrete Jersey Barrier



50-219-015_2022_15_CDI_SW Rail end Spall with Exposed Rebar



50-219-015_2022_16_CDI_Steel Channel Attached to Backside of NW Railing



50-219-015_2022_17_CDI_Underside of South Edge of Slab in West Span with Stalactites



50-219-015_2022_18_CDI_Underside of South Edge of Slab in East Span with Stalactites



50-219-015_2022_19_CDI_Underside of North Edge of Slab in West Span
with Stalactites



50-219-015_2022_20_CDI_Underside of North Edge of Slab in East Span
with Stalactites



50-219-015_2022_21_CDI_South Edge of Slab with Efflorescence and Minor Stalactites



50-219-015_2022_22_CDI_North Edge of Slab with Active Stalactite Dripping



50-219-015_2022_23_CDI_Center Bent



50-219-015_2022_24_CDI_North Bent Column Scaling



50-219-015_2022_25_CDI_Center Bent South Column Efflorescence Buildup



50-219-015_2022_26_CDI_Upstream Channel looking North



50-219-015_2022_27_CDI_Downstream Channel looking South



50-219-015_2022_28_CDI_Riprap in front of West Abutment



50-219-015_2022_29_CDI_Riprap in front of East Abutment

CHANNEL PROFILE


MINNEHAHA COUNTY

STR. NO. 50-219-015

MEASUREMENTS TAKEN FROM THE TOP OF: **RAIL**
 MEASUREMENTS TAKEN ON THE INLET SIDE OF THE STRUCTURE: **NORTH**

WATER ELEV: **9.7**

		2016	2018	7/1/2020	6/16/2022	ABUT./BENT	
West End	0	10.8	10.5	10.6	10.4	1	0
	5	11.1	11.0	12.3	11.2	2	16.5
	10	11.2	11.2	12.9	12.9	3	33
	15	11.3	11.3	12.6	12.4		
	20	11.0	11.1	13.5	12.8		
	25	10.8	10.9	13.9	12.2		
30	10.3	10.4	13.6	10.6	Top of RAIL to bottom of Superstructure 3.6 ft.		
East End	33	9.8	9.8	10.5	9.8		



Note: No Construction Plans are enclosed in SDDOT bridge inspection file.



General Bridge Data		Status
(8) STR NO : 50-219-015	(27) YEAR BUILT : 1938	SUFF RATE : 35.30
(7) FACILITY : JASPER ST, HWY 104	(106) RECONSTR : (1)	FED SUFF RATE : 49.90
(6) FEAT INTER : TRIB TO BIG SIOUX RV	(49) STR LENGTH : 36.30 ft	FED SR DATE : 03/14/2022
(9) LOCATION : 1.5E & 0.2N DELL RAPIDS	NBIS BRIDGE LENGTH : 32.30 ft	DEFICIENCY : S
INTERCHANGE : N	(48) MAX SPAN LENGTH : 18.10 ft	CANDIDATE : P
SECTION(S) : 10 -1 -1 -1	(43A) MATERIAL : 2 Concrete Continuous	
TOWNSHIP(S) : 104N -1	(43B) DESIGN : 01 Slab	Deck Data
RANGE(S) : 49W -1	SD STR TYPE : X020	(108A) WEARING SURFACE : 6 Bituminous
(2) REGION : Mitchell	(107) DECK STR TYPE : 1 Concrete-Cast-in-Place	DECK PROTECTION : None
(3) COUNTY : 50 MINNEHAHA	(52) DECK WIDTH : 27.30 ft	OVERLAY THICKNESS : 12.00 in
(21) CUSTODIAN : 2 County Hwy Agency	(51) BRIDGE RDWY WIDTH : 24.30 ft	DECK DELAM AREA : 0.00 sq ft
(22) OWNER : 2 County Hwy Agency	(32) APPR RDWY WIDTH : 24.00 ft	DECK DELAM DATE :
MAINT PROJ :	(50A) LT SIDEWALK WIDTH : 0.00 ft	DECK SURVEY :
(42A) SERV TYPE ON : 1 Highway	(50B) RT SIDEWALK WIDTH : 0.00 ft	CHLORIDE : N
(42B) SERV TYPE UND : 5 Waterway	(34) SKEW : 30.00°	RESTEEL DEPTH : N
(103) TEMP STRUCTURE : Unknown (NBI)	SKEW DIR : L	ELECTRO POTENT : N
(99) BORDER BRIDGE STR NO : -1	(45) NO MAIN SPANS : 2	Load Rating Data
(98A) NEIGHBOR STATE : Unknown (P)	(46) NO APPR SPANS : 0	(41) OPER STATUS : A Open, no restriction
(98B) PERCENT SHARE : -2.00	(31) DESIGN LOAD : 0 Unknown	(66) INV HS20 : 21.60 tons
Highway Carried (NBI 5)	(33) BRIDGE MEDIAN : 0 No median	(65) METHOD : 0 Field eval and docs
(5B) ROUTE PREFIX : 4 County Hwy	(35) STR FLARED : 0 No flare	(64) OP HS20 : 36.00 tons
(5C) LEVEL OF SERVICE : 1 Mainline	Box Culvert Data	(63) METHOD : 0 Field eval and docs
(5D) ROUTE NUMBER : 00000	BOX CULVERT SIZE : 0 X 0 X 0	TRUCK TYPE 3 : 24.00 tons
(5E) DIRECT SUFFIX : 0 N/A (NBI)	FILL HT OVER BOX : 0.00 ft	TRUCK TYPE 3S2 : 40.00 tons
MRM ENGLISH : 0.00	LENGTH OF LONGEST CELL : 0.00 ft	TRUCK TYPE 3-2 : 46.00 tons
POSTED SPEED : 55 MPH	Rail Data	NRL : 40.00 tons
SCHOOL BUS RT : Y	(36) SAFETY FEAT : 0000	SHV-4 : 27.00 tons
MAIL RT : Y	BRIDGE RAIL 1 : 11 - CONC PIGEON HOLE RAIL	SHV-5 : 31.00 tons
(104) NHS SYSTEM : 0 Not on NHS	RAIL TRANS 1 : 00 - NO TRANSITION PROVIDED	SHV-6 : 34.80 tons
FA ROUTE : 6250	APPR RAIL 1 : 00 - NO APPROACH RAIL	SHV-7 : 38.80 tons
(26) FUNC CLASS : 07 Rural Mjr Collector	APPR RAIL TERM 1 : 00 - NO TERMINALS PROVIDED	EV2 : tons
(28A) LANES : 2	NBI Prop Work	EV3 : tons
(102) DIRECTION TRAFFIC : 2 2-way traffic	(75A) WORK TYPE : 31 Repl-Load Capacity	BARS NO : JDG
(105) FED LANDS HWY : 0 N/A (NBI)	(75B) WORK BY : 1 Contract	Hydraulics
(19) DETOUR : 9.00 mi	(76) IMPROV LENGTH : 191.60 ft	DRAINAGE AREA : 1.99 sq mi
(29) ADT TOTAL : 1111.00	(94) BRIDGE IMPROV COST : \$274,684.00	OBSERV HW ELEV : 0.00 ft
(30) YEAR OF ADT : 2021	(95) RDWAY IMPROV COST : \$27,468.00	YEAR : 01/01/1901
(109) % TRUCK : 3.00 %	(96) TOTAL PROJECT COST : \$462,092.00	DESIGN FREQ : 0.00
(53) MIN V CLR RT : 99.99 ft	(97) YEAR OF IMPROV COST : \$2,018.00	DESIGN FLOW : 0.00 cfs
(53) MIN V CLR LT : 0.00 ft	(114) ADT FUTURE : 1400.00	DESIGN VELOCITY : 0.00 fps
(10) MAX V CLR RT : 99.99 ft	(115) YEAR OF ADT FUTURE : 2036	DESIGN AREA : 0.00 sq ft
(10) MAX V CLR LT : 0.00 ft	Steel Paint	DESIGN YEAR :
(47) HORIZ V CLR RT : 24.00 ft	UNDERCOAT :	DESIGN HW ELEV : ft
(47) HORIZ V CLR LT : 0.00 ft	TOPCOAT :	100 YEAR FLOW : 0.00 cfts
GIS Data	YEAR :	100 YEAR HW ELEV : ft
LATITUDE : 43.82597	COLOR :	V MAX : fps
LONGITUDE : -96.68737		SCOUR SCREENING : 2
DATE : 03/28/2016		SCOUR RATING : U
COMMENT : Calculated GIS INFO		TOPEKA SHINER : N
		Rail Paint
		UNDERCOAT :
		TOP COAT :
		YEAR :

COLOR :

Highway Carried (Under Record)

(5A) RECORD TYPE : (54) MIN V CLR RT :
 (5B) ROUTE PREFIX : (54) MIN V CLR LT :
 (5C) LEVEL OF SERVICE : (10) MAX V CLR RT :
 (5D) ROUTE NUMBER : (10) MAX V CLR LT :
 (5E) DIRECT SUFFIX : (47) HORIZ CLR RT :
 MRM : (47) HORIZ CLR LT :
 ADM JUR : (55) OUT UNDCLR RT :
 (104) NHS SYSTEM : (55) OUT UNDCLR LT :
 FA ROUTE : (56) MED UNDCLR RT :
 (26) FUNC CLASS : (56) MED UNDCLR LT :
 (28B) LANES :
 (101) DIRECTION OF TRAFFIC :
 (19) DETOUR LENGTH : mi
 (29) ADT :
 (30) ADT YEAR :

Project Number	PCN	Date Done
NA	none	01/01/1938

Inspection

GENERAL COMMENT : -1
 REGION COMMENT : -1
 FREE COMMENT : -1

INSPECTION TYPE	LAST INSPECTION DATE	REQUIRED	INSPECTION FREQUENCY	NEXT INSP DATE
NBI	06/16/2022		24 month(s)	06/16/2024
FRACTURE CRITICAL	NA	N	NA	NA
UNDERWATER	NA	N	NA	NA
SPECIAL	NA	N	NA	NA
ELEMENT INSPECTION	06/16/2022		24 month(s)	06/16/2024

INSPKEY : NJQN
 APPRAIS BY : CLB
 APPRAIS DATE : 10/03/2022
 QA INSPECTOR :
 QA INSP DATE :
 LAST INSPECTION BY :
 CONSULTANT CODE : CIVIL DESIGN

Condition Ratings

(58) DECK : 4
 (59) SUPER : 4
 (60) SUB : 5
 (62) CULVERT : N
 (113) SCOUR : U
 (61) CHANNEL : 7
 APPROACH : 7 -1

Appraisal Ratings

STR APPR : 4 -1
 DECK GEOM : 4 -1
 UNDERCLR : N -1
 WATERWAY : 7 -1
 APPR ALIGN : 8 -1
 BR POST : 5 LEGAL LOADS
 SCOUR SCREENING : 2
 SCOUR RATING : U

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Re Concrete Slab	MAIN	38	2	991.00	sq.ft	0.00	921.00	70.00	0.00
<p>Cast-in-place concrete - The top surface of the concrete slab is not visible due to the gravel and bituminous overlay.</p> <p>Cast-in-place concrete - Transverse cracks, longitudinal cracks, and areas of map cracking are evident throughout. A significant amount of efflorescence is evident along both the north and south side (outside 1 ft edge) of the concrete slab in the both spans. The efflorescence along edges of slab has advanced to active stalactites dripping along both edges of the east and west spans. The south edge has minor stalactites and the north edge has moderate to substantial stalactites evident. Scaling and some spalls are evident along the bottom exterior edges of the slab at the corners of the structure.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	360.00	sq.ft	0.00	328.00	32.00	0.00
-									
Efflorescence/Rust Staining	MAIN	1120	2	288.00	sq.ft	0.00	250.00	38.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	343.00	sq.ft	0.00	343.00	0.00	0.00
-									
AC w/o Membrane Overlay	MAIN	814	2	882.00	sq.ft	882.00	0.00	0.00	0.00
Gravel base with bituminous surfacing - Approximate 12-inch average total depth. The bituminous surfacing is relatively smooth.									
Re Conc Column	MAIN	205	2	4.00	each	3.00	1.00	0.00	0.00
<p>Cast-in-place concrete - There are four (4) concrete columns at the bent. A significant amount of scaling is evident on the north column at the bent. There does not appear to be a significant amount of section loss or exposed reinforcing steel at this time. Vertical hairline cracking is evident in the columns. The south column has efflorescence buildup along the south face which appears to be coming from the underside of slab and from the scaling bent cap.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	1.00	each	0.00	1.00	0.00	0.00
-									
Re Conc Abutment	MAIN	215	2	54.00	ft	44.00	10.00	0.00	0.00
<p>Cast-in-place concrete - Some vertical hairline cracks and some scaling along the bottom of the backwalls are evident. Some efflorescence is evident along the top of the backwalls at the ends of the backwalls.</p> <p>Cast-in-place concrete - A moderate to heavy amount of scaling and areas of horizontal hairline cracking are evident on the tops of the wingwalls. Overall, the wingwalls appear to be in satisfactory condition.</p>									
Cracking (RC and Other)	MAIN	1130	2	10.00	ft	0.00	10.00	0.00	0.00
-									
Re Conc Pier Cap	MAIN	234	2	27.00	ft	19.00	8.00	0.00	0.00
<p>Cast-in-place concrete - The bent cap consists of a concrete beam. There are vertical hairline cracks evident between and over the columns. Significant scaling is observed along the north and south ends of the cap.</p>									
Delamination/Spall/Patched Area	MAIN	1080	2	2.00	ft	0.00	2.00	0.00	0.00
-									
Cracking (RC and Other)	MAIN	1130	2	6.00	ft	0.00	6.00	0.00	0.00
-									
Re Conc Bridge Railing	MAIN	331	2	72.00	ft	0.00	57.00	6.00	9.00
<p>The railings consist of reinforced concrete pigeon hole railings. A moderate to significant amount of scaling is evident throughout with areas of exposed reinforcing steel. It appears a significant vehicle impact occurred at the west end of the north railing. The top concrete railing member, some of the spindles, and the concrete curb have been significantly damaged. A portable concrete barrier curb section has been placed off the west end of the north railing. Steel channels have been installed along the outside face of the railing and are anchored into the concrete barrier curb section. A steel plate has been installed along the inside face of the railing. The steel channels and steel plate are bolted together with bolts running through the pigeon holes. The concrete barrier curb section and steel channels do not provide a railing with the same amount of strength as the original concrete bridge railing before the vehicle impact, but they are providing additional strength to what is provided by the damaged concrete bridge railing. The damaged section of the north concrete bridge railing needs to be completely replaced.</p>									

Elements	Unit	ID	Env	Quantity	Units	Q 1	Q 2	Q 3	Q 4
Delamination/Spall/Patched Area	MAIN	1080	2	57.00	ft	0.00	57.00	0.00	0.00
-									
Damage	MAIN	7000	2	15.00	ft	0.00	0.00	6.00	9.00
-									

Action	Agency Status	Agency Priority	Assigned to	Rec. Date	Str No	Assigned To	Notes	Target Year
			No					