
Figure 2 - Project Summary





A: Seasonal flooding is a travel hazard



B: Slow equipment, buggies, and other non-motorized traffic share the travel lane



C: Steep embankments are common throughout the highway corridor



D: Submerged vehicle at Roy Lake



E: Extensive chip sealing on Blair Road shows need for pavement rehabilitation